



# JACKSON

## ROBBINS AUTO TOPS PRICE LIST

EFFECTIVE AUGUST 15, 2016



**ROBBINS<sup>®</sup>**  
**AUTO TOP COMPANY, INC.**

*Since 1843*



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



YR	PART NO.	ALFA ROMEO	KV	AT	ST	MISC	HRS.	B/H		
1956-59	2012	Giulietta Top w/plastic window SWB, no wind wing	\$722	\$782	\$1,056		5			
1957-59	2013	Spider 2000 Top w/plastic window	\$836	\$908	\$1,140		5			
1960-62	2014	Spider 2000 Top, w/Plastic Window	\$771	\$837	\$1,101		5			
1960-61	2015	Giulietta Top w/plastic window	\$722	\$782	\$1,056		5			
1962-63	2016	Giulietta Top w/plastic window LWB wind wing on doors	\$722	\$782	\$1,056		5			
1963-66	2017	Spider 2600 Top, w/plastic window	\$810	\$880	\$1,180		5			
1964-66	2018	Giulietta, 1600 Spider/Sprint Top, w/plastic window	\$749	\$813	\$1,079		5			
1966	2019	GTC 4 Seat Top with plastic window LWB wind wing on doo	\$982	\$1,067	\$1,343		6.5			
1967-70	2020	Duetto Spider 1600-1750 Top, w/plastic window	\$734	\$796	\$1,098		5			
1971-94	2021	Spider 1750, 2000 Top, w/plastic window, non padded Quart	\$704	\$762	\$1,098		5			
1971-94	2021R	Spider 1750, 2000 2021 Top w/ Hand-Rolled Cloth Bindin	\$711	\$770	\$1,113		5			
1971-94	2021RV	Spider 1750, 2000; 2021 Top w/ Hand-Rolled Vinyl Binding	\$704	\$762	\$1,098		5			
1971-94	2080	Spider 1750, 2000 Top ,w/plastic window, w/padded Quarters	\$822	\$892	\$1,180		5			
1971-94	2080R	Spider 1750, 2000; 2080 Top w/Hand Rolled Cloth Binding	\$902	\$979	\$1,261		5			
1971-94	2080RV	Spider 1750, 2000; 2080 Top w/Hand Rolled Vinyl Binding	\$889	\$967	\$1,246		5			
1967-70	1020	Duetto Spider 1600-1750 Tonneau Cover w/side Zippers	\$674	\$732	\$1,187		3			
1971-94	1021	Alfa Spider 1750, 2000 Tonneau Cover w/side Zippers	\$655	\$712	\$1,168		3			
1971-94	B1021	Alfa Spider 1750, 2000 Boot non original	\$567	\$616	\$890		2			
1995-03	2081PC	Spider Combo Top, Front & Plastic Window Section	\$877	\$954	\$1,290		8			
1995-03	2081	Spider Top, Front Section Only	\$615	\$666	\$991		6			
1995-03	PC2081	Plastic Window Section Only for 2081	\$375	\$405	\$432		2			
1995-03	HL2081	Spider Headliner w/plastic retainer				\$670	5			
1971-94	CBLRS	Alfa & Fiat Universal side tension cables				\$155				
AUDI										
YR	PART NO.	Audi Cabriolet	AT	ST	TW	GR	MISC	HRS.	B/H	
1992-98	3200C	Audi Cabriolet Top w/plastic window	\$1,345	\$1,441	\$1,500	\$1,638		8		
1992-98	HLM3200	Cabriolet HEADLINER w/sewn in retainers, manual top only.					\$697	4		
1992-98	HLP3200	Cabriolet HEADLINER w/sewn in retainers ,power top only					\$697	4		
YR	PART NO.	Audi A4 and S4	PERMALOK Bonded Window	AT	ST	TWR	A5	A5B	HRS.	B/H
2003-09	3201C	Audi A4/S4 Cabriolet Top w/Heated Glass original OEM retair	\$1,349	\$1,425	\$1,770	\$2,135	\$2,389		8	
YR	PART NO.	Audi TT	PERMALOK Bonded Window	AT	ST	TWR	A5	HRS.	B/H	
2000-06	3220C	Audi TT Roadster Top with Heated Glass	\$1,298	\$1,374	\$1,495	\$1,689		7		
2007-13	3221C	Audi TT Roadster Top with Heated Glass	CALL FOR PRICES					7		
YR	PART NO.	AUSTIN HEALEY	CG	EF	BS	ST	HRS.	B/H		
1953-56	2108R	Roadster 100-4 BN-1, BN-2 Top	\$1,041	\$1,133	\$1,392	\$1,583	5			
1954-56	1103	1954-56 100-4 BN-1, BN-2 Tonneau, Long	\$612	\$664	\$992	\$1,241	3			
1954-56	1103A	1954-56 100-4 BN-1, BN-2 Tonneau, Short	\$612	\$664	\$992	\$1,241	3			
1954-56	1103BR	1956 100-4 BN-2 Tonneau, Original Style	\$743	\$809	\$1,125	\$1,271	3			
1957-62	2104	100-6 BN-6, 3000 BN-7 Top	\$748	\$812	\$1,128	\$1,290	5			
1957-62	1104	1957-62 100-6 BN-6, 3000 BN-7, Short style tonneau cover	\$612	\$664	\$992	\$1,241	3			
1957-62	1104A	1957-62 100-6 BN-6, 3000 BN-7, Long style tonneau cover	\$625	\$679	\$1,007	\$1,256	3			
1957-62	1105	1957-62 100-6 BN-4, 3000 BT-7 Tonneau	\$684	\$745	\$1,066	\$1,227	3			
1957-59	2105	100-6 BN-4, 3000 BT-7 Top	\$777	\$843	\$1,159	\$1,305	5			
1957-58	2105A	100-6 BN-4 Longbridge Car Top	\$801	\$868	\$1,180	\$1,326	5			
1960-62	2155	3000 BT-7, 4 Seat Top	\$777	\$843	\$1,159	\$1,305	5			
1962-63	2156	3000 BJ-7, 4 Seat Top	\$748	\$812	\$1,128	\$1,290	5			
1963-68	1156	1963-68 3000 BJ-7, 4 Seat Tonneau	\$699	\$761	\$1,080	\$1,241	3			
1963-68	2156A	3000 BJ-8, 4 Seat Top	\$777	\$843	\$1,159	\$1,305	5			
1963-68	1157	1963-68 3000 BJ-8, 4 Seat Tonneau	\$890	\$970	\$1,271	\$1,373	3			
1963-68	B1157	1963-68 Austin Healey 3000 BJ-8, 4 Seat Top Boot	\$905	\$987	\$1,285	\$1,387	2			
YR	PART NO.	SPRITE	CG	EF	BS	ST	HRS.	B/H		
1958-60	2106	AH Sprite Top, Metal Rod on Windshield	\$689	\$746	\$1,070	\$1,305	5			
1958	2106A	AH Sprite Top, Snaps on Windshield	\$689	\$746	\$1,070	\$1,305	5			
1958-61	1106	1958-61 Austin-Healey Tonneau, Short Style	\$617	\$670	\$987	\$1,247	3			
1958-61	1106A	1958-61 Austin-Healey Tonneau, Long Style	\$581	\$632	\$962	\$1,212	3			
1961-64	2166	Austin-Healey Sprite MK II Top	\$704	\$762	\$1,100	\$1,262	5			
1961-64	1166	Austin-Healey Sprite MK II Tonneau Cover	\$625	\$679	\$1,007	\$1,146	3			
1965-66	2167	Austin-Healey Sprite MK III Top	\$704	\$762	\$1,100	\$1,262	5			
1965-66	1167	Austin-Healey Sprite MK III Tonneau Cover	\$597	\$647	\$1,007	\$1,110	3			
1965-66	1167F	Austin-Healey Sprite MK III Tonneau with hold down flaps	\$684	\$745	\$1,066	\$1,241	3			



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1967-70	2167A	Austin-Healey Sprite MK IV Top		\$704	\$762	\$1,100	\$1,262		5	
1967-70	1167A	Austin-Healey Sprite Mk IV Tonneau Cover		\$670	\$728	\$1,066	\$1,228		3	
1970-71	2168	Austin-Healey Sprite MK IV Top		\$704	\$762	\$1,100	\$1,262		5	
1970-71	1168H	Austin-Healey Sprite MK IV Tonneau Cover with headrest p		\$684	\$745	\$1,066	\$1,241		3	
<b>YR</b>	<b>PART NO.</b>	<b>BENTLEY</b>		<b>CG</b>	<b>AT</b>	<b>BS</b>	<b>ST</b>	<b>TW</b>	<b>HRS.</b>	<b>B/H</b>
1987-92	2450R	Bentley Top with Plastic Window (specify Gray or Tan window		\$1,700	\$1,858	\$2,491	\$2,609	\$2,858	16	23.5
		<b>BMW</b>								
<b>YR</b>	<b>PART NO.</b>	<b>E30 Baur Tops 1977-1991</b>		<b>AT</b>	<b>SG</b>	<b>GR</b>			<b>HRS.</b>	<b>B/H</b>
1977-82	2708	Baur Top Rear Section, w/plastic window		\$893	\$1,144	\$1,231			5	
1983-91	2709	Baur Top Rear Section, w/plastic window		\$893	\$1,144	\$1,231			5	
		Note: To cover the front hatch & windshield frame order 1.5yds of topping								
<b>YR</b>	<b>PART NO.</b>	<b>(E30) 1987-1993 318i/320i/323i/325i/M3 Cabriolet</b>		<b>AT</b>	<b>ST</b>	<b>TW</b>	<b>GR</b>	<b>MISC</b>	<b>HRS.</b>	<b>B/H</b>
1987-93	2710NC	E-30 Top, w/plastic window ,Manual , w/double fold cloth bindi		\$1,022	\$1,208	\$1,251	\$1,417		8	23.25
1987-93	2710NR	E-30 Top, w/plastic window ,Manual , w/hand rolled cloth bindi		\$1,113	\$1,364	\$1,423	\$1,583		8	23.25
1987-93	2711NC	E-30 Top w/plastic window, Power, w/double fold cloth binding		\$1,022	\$1,208	\$1,251	\$1,417		8	23.25
1987-93	2711NR	E-30 Top w/plastic window, Power, w/hand-rolled cloth binding		\$1,113	\$1,364	\$1,423	\$1,583		8	23.25
1987-93	RT2710	Black Metal Header Bow Retainer for 87-93 BMW E30						\$360		
1987-93	TS2710	E30 Tension Straps						\$550		
<b>YR</b>	<b>PART NO.</b>	<b>(E36) 1977-1991 318i(c)/320i(c)/325i(c)/328i(c)/M3 Cabriolet</b>		<b>AT</b>	<b>ST</b>	<b>TW</b>		<b>MISC</b>	<b>HRS.</b>	<b>B/H</b>
1994-95	2712C	E36 Top w/plastic window; Relief Pockets at Quarters		\$985	\$1,048	\$1,349			9	
1994-99	2713C	E36 Top w/plastic window, No Relief Pockets		\$965	\$1,030	\$1,328			9	
		**TS2712 Tension Straps required to install this top on 1994-95 E36**								
1994-99	TS2712	E36 Tension Straps						\$550		
1994-99	CBL2712	Side Tension Cables for 2712C and 2713C Tops						\$155		
<b>YR</b>	<b>PART NO.</b>	<b>(E46) 2000-2006 318Ci/320Cd/320Ci/323Ci/325Ci/330Ci/M3</b>		<b>AT</b>	<b>ST</b>	<b>TWR</b>	<b>A5</b>		<b>HRS.</b>	<b>B/H</b>
2000-06	2714C	E46 Top with Heated Glass. OEM style rear plastic retainer		\$1,556	\$1,717	\$1,849	\$1,995		10	
<b>YR</b>	<b>PART NO.</b>	<b>(E64) 2005-2009 630i/645i/650i/M6 Cabriolet</b>		<b>ST</b>	<b>TWR</b>				<b>HRS.</b>	<b>B/H</b>
2005-09	2765	E64 Top, fits to existing glass		\$2,096	\$2,463				12	
<b>YR</b>	<b>PART NO.</b>	<b>(E88) 2008-2014 128i/135i</b>		<b>A5B</b>					<b>HRS.</b>	<b>B/H</b>
2008-14	2718C	I Series Top with Heated Glass and rain guards		\$2,553					10	
<b>YR</b>	<b>PART NO.</b>	<b>BMW Z3 Series</b>		<b>AT</b>	<b>ST</b>	<b>TW</b>	<b>A5</b>	<b>MISC.</b>		
1996-02	2750C	BMW Z3 Roadster Top with green tint plastic window. Includes OEM style SHORT and LONG side tension cables. MADE WITH REAR QUARTER VERTICAL RELIEF POCKETS. SEWN IN PLASTIC RETAINERS		\$875	\$947	\$1,041	\$1,144		7	
1996-02	2751C	BMW Z3 Roadster Top with green tint plastic window. Made with non original Rain Gaurds Includes OEM style SHORT and LONG side tension cables. SEWN IN PLASTIC RETAINERS, REAR RELIEF POCKETS		\$1,022	\$1,098	\$1,221	\$1,384		7	
1996-02	TS2750	BMW Z3 Tension Staps						\$279		
To 12/96	CBL2750S	Side Tension cables, SHORT						\$184		
12/96-2002	CBL2750L	Side tension cables, LONG						\$184		
<b>YR</b>	<b>PART NO.</b>	<b>BMW Z4 Series</b>		<b>AT</b>	<b>ST</b>	<b>TWR</b>	<b>A5</b>		<b>HRS.</b>	<b>B/H</b>
2003-08	2752C	BMW Z4 Roadster Top with Heated Glass. Made with OEM style rear crimp-on retainer and b-pillar retainers.		\$1,336	\$1,499	\$1,723	\$1,932		8	
<b>YR</b>	<b>PART NO.</b>	<b>BUICK</b>		<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1959-60	7505	Electra/Invicta/LeSabre Top, Front Section Only		\$655	\$1,221				6	23
1959-60	PC7505	Plastic Window Section Only for 7505 Top		\$312	\$459				3	
1961-64	7506	Electra/Invicta/LeSabre/Wildcat Top, Front Section Only		\$655	\$1,221				6	25
1961-64	PC7506	Plastic Window Section Only for 7506 Top		\$308	\$459				3	
1961-64	GL402	Non Htd Glass Wndw Section Only for 7506 Top. See Web or		\$737	\$933				3	
1962-63	7301	Special, Skylark, Grand Sport Top, Front Section Only		\$644	\$1,221				6	21.75
1962-63	PC7301	Plastic Window Section Only for 7301 Top		\$308	\$456				3	
1964-65	7302	Special, Skylark, Grand Sport Top, Front Section Only		\$627	\$1,221				6	20.5
1964-65	PC7302	Plastic Window Sectiopn Only for 7302 Top		\$308	\$456				3	
1966-67	7303	Special, Skylark, Grand Sport Top, Front Section Only		\$611	\$1,180				6	22
1966-67	PC7303	Plastic Window Section Only for 7303 Top		\$308	\$456				3	
1962-67	GL401	Non Heated Glass Window Section Only for 7301,7302,7303		\$746	\$933				3	
1965-72	PD6572	Original Style Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).						\$427		
1965-72	CBL7303	Side Tension Cables for 7303 Top						\$155		



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1965-70	7507PC	LeSabre/Wildcat Top, Combo Front & Plastic Window Sector	\$880	\$1,437	8	27.5	
1965-70	7507T5	LeSabre/Wildcat Top, Combo Fnt & Non Htd Glass Wndw Se	\$1,204	\$1,729	8	27.5	
1965-70	7507T7	LeSabre/Wildcat Top, Combo Fnt & Non Htd Glass Window Secti	\$1,204	\$1,729	8	27.5	
1965-70	7607PC	Electra Top, Combo Front & Plastic Window Sections w/Zippe	\$850	\$1,407	8	27.5	
1965-70	7607T5	Electra Top, Combo Front & Non Heated Glass Window Secti	\$1,204	\$1,770	8	27.5	
1965-70	7607T7	Electra Top, Combo Front & Non Heated Glass Window Secti	\$1,204	\$1,770	8	27.5	
1965-70	7507	LeSabre/Wildcat Top, Front Section Only	\$627	\$1,180	6	27.5	
1965-70	7607	Electra Top, Front Section Only	\$627	\$1,180	6	27.5	
1965-70	PC7507	Plastic Window Section Only for 7507 and 7607 Top	\$329	\$476	3		
1965-70	TN465	Non-Heated Glass Window Section Only, w/Zipper for 7507 ar	\$706	\$852	3		
1965-70	TN467	Non-Heated Glass Window Section Only, No Zipper for 7507	\$694	\$841	3		
1965-70	CBL7507	Side Tension Cables for 7507 Top			\$155		
1965-70	CBL760	Side Tension Cables for 7607/7608 Top			\$155		
1968-72	7304PC	Special/Skylark/ Gran Sport Top, Combo Fnt & Plastic Wndw	\$777	\$1,343	8	Fixed	
1968-72	7304APC	Special/Skylark/ Gran Sport Top, Combo Fnt & Plastic Wndw	\$777	\$1,343	8	20.75	
1968-72	7304TN	Special/Skylark/ Gran Sport Top, Combo Fnt & Non Htd Glas	\$1,161	\$1,770	8	Fixed	
1968-72	7304ATN	Special/Skylark/ Gran Sport Top, Combo Fnt & Non Htd Glas	\$1,230	\$1,839	8	20.75	
		For Floating Bow					
1968-72	7304	Special/Skylark/Gran Sport Top, Front Section Only	\$591	\$1,098	6	Fixed	
1968-72	7304A	Special/Skylark/ Gran Sport Top, Frnt Sec Only, Floating Bc	\$644	\$1,180	6	20.75	
1968-72	PC7304	Plastic Window Section Only for 7304 and 7304A Tops	\$262	\$408	3		
1968-72	TN404	Non-Heated Glass Window Section Only for 7304 and 7304A	\$685	\$831	8		
1968-72	WB7304	Well Liner for 7304 and 7304A Tops			\$377		
1965-72	PD6572	Original Style Tapered Top Pads for GM Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).			\$427		
1968-72	CBL7304	Side Tension Cables for 7304 and 7304A Tops			\$155		
YR	PART NO.	"SCISSOR TOP"	KV	SF	MISC.	HRS.	B/H
1971-76	7509PC	LeSabre/Centurion Top, Combo Front & Plastic Window Sec	\$924	\$1,509		11	
1971-76	7509TN	LeSabre/Centurion Top, Combo Fnt & Non Htd Glass Wndw	\$1,144	\$1,712		11	
		Reuse window brackets					
1971-76	7509HD	LeSabre/Centurion Top, Combo Fnt & Htd Glass Wndw Sec	\$1,409	\$2,015		11	
		Reuse window brackets					
1971-76	7509	LeSabre/Centurion Top, Front Section Only	\$611	\$1,098		8	
1971-76	TN409	Non-Heated Glass Window Section Only for 7509. Reuse win	\$706	\$850		3	
1971-76	HD409	Heated Glass Window Section Only for 7509 Top	\$982	\$1,128		3	
1971-76	PC7509	Plastic Window Section Only for 7509 Top	\$399	\$545		3	
1971	CBL750	GM Scissor Top Side Tension Cables			\$237		
1972-76	CBL7509	GM Scissor Top Side Tension Cables			\$208		
1971-76	WB7509	Well Liner for 7509 Top			\$381		
YR	PART NO.	RIVIERA	KV	SF	MISC.	HRS.	B/H
1983-86	7401	Riviera Top, Front Section Only	\$726	\$1,221		6	16.5
1983-86	TN410	Non-Heated Glass Window Section Only for 7401 Top	\$678	\$826		3	
1983-86	HD410	Heated Glass Window Section Only for 7401 Top	\$954	\$1,101		3	
1983-86	PC7401	Plastic Window Section Only for 7401 Top	\$390	\$537		3	
YR	PART NO.	CADILLAC	KV	SF	MISC.	HRS.	B/H
1959-60	7505	Cadillac Top, Front Section Only	\$655	\$1,221		6	23
1959-60	PC7505	Plastic Window Section Only for 7505 Top.	\$312	\$459		3	
1961-64	7506	Eldorado Top, Front Window Section Only	\$655	\$1,221		6	25
1961-64	PC7506	Plastic Window Section Only for 7506 Top.	\$312	\$459		3	
1961-64	GL402	Non Heated Glass Wndw Section Only for 7506 Top. See C	\$737	\$933		3	
1965-70	7607PC	Eldorado/Coupe de Ville Top, Combo Fnt & Plastic Wndw Ser	\$850	\$1,202		8	27.5
1965-70	7607T5	Eldorado/Coupe de Ville Top, Combo Fnt & Non Htd Glass W	\$1,204	\$1,770		9	27.5
1965-70	7607T7	Eldorado/Coupe de Ville Top, Combo Fnt & Non Htd Glass W	\$1,204	\$1,770		9	27.5
1965-70	7607	Eldorado/Coupe de Ville Top, Front Section Only	\$627	\$1,180		6	27.5
1965-70	PC7507	Plastic Window Section Only for 7607 Top.	\$329	\$476		3	
1965-70	TN465	Non-Heated Glass Window Section Only w/Zipper for 7607 T	\$706	\$852		6	
1965-70	TN467	Non-Heated Glass Window Section Only, no Zipper for 7607	\$694	\$841		6	
1965-72	PD6572	Original Style Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).			\$427		
1965-70	CBL760	Side Tension Cables for 7607/7608 Top			\$155		
1971-76	7509PC	Eldorado Top, Combo Front & Plastic Window Sections	\$924	\$1,509		8	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1971-76	7509TN	Eldorado Top, Combo Fnt & Non Htd Glass Wndw . Reuse wi	\$1,161	\$1,729				8	
1971-76	7509HD	Eldorado Top, Combo Fnt & Htd Glass Wndw .Reuse window	\$1,409	\$2,015				8	
1971-76	7509	Eldorado Top, Front Section Only	\$611	\$1,098				8	
1971-76	TN409	Non-Heated Glass Window Section Only for 7509. Reuse win	\$706	\$850				3	
1971-76	HD409	Heated Glass Window Section for 7509 Top	\$982	\$1,128				3	
1971-76	PC7509	Plastic Window Section Only for 7509 Top	\$399	\$545				3	
1971	CBL750	GM Scissor Top Side Tension Cables						\$237	
1972-76	CBL7509	GM Scissor Top Side Tension Cables						\$208	
1971-76	WB7509	Well Liner for 7509 Top						\$381	
<b>YR</b>	<b>PART NO.</b>	<b>Hess &amp; Eisenhardt</b>	<b>KV</b>	<b>SF</b>				<b>HRS.</b>	<b>B/H</b>
1978-79	7510	Coupe de Ville - Hess & Eisenhardt Top, Front Section Only	\$713	\$1,140				6	
1978-79	PC7510	Plastic Window Section Only for 7510 Top	\$419	\$571				3	
1980-85	7403	Eldorado - Hess & Eisenhardt Top, Front Window Section On	\$706	\$1,221				6	
1980-85	PC7403	Plastic Window Section Only for 7403 Top	\$390	\$537				3	
1983-85	7402	Eldorado - A.S.C Top, Front Section Only	\$726	\$1,221				6	
1983-85	TN415	Non-Heated Glass Window Section Only for 7402 Top	\$678	\$826				3	
1983-85	HD415	Heated Glass Window Section Only for 7402 Top	\$1,027	\$1,198				3	
1986-87	7512	Coupe De Ville, Kar Kraft Top, Front Section Only. Window n	\$706	\$1,221				6	
<b>YR</b>	<b>PART NO.</b>	<b>CADILLAC ALLANTE</b>	<b>SF</b>	<b>SG</b>	<b>GR</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1987-93	7409R	Cadillac Allante Top, Front Section Only. w/Escutcheons & C:	\$1,487	\$1,556	\$1,753			8	
1987-93	HL7409	Cadillac Allante Headliner (Black Dobby)					\$667		
1987-93	ESCUT	Four Escutcheons (corner trim pieces) for Cadillac Allante	\$186	\$208	\$222				
1987-93	CBL7409	Allante Front & Rear Hold Down cables					\$198		
1987-93	RT7409	Retainer (Replaces Velcro) 1988 Only Allante.					\$121		
<b>YR</b>	<b>PART NO.</b>	<b>CHEVROLET</b>	<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1955-57	7502	Chevrolet Bel-Air Top, Front Section only	\$743	\$1,180				6	20.5
1955-57	PC7502	Plastic Window Section Only for 7502 Top	\$329	\$476				3	
1958	7504	Chevrolet Impala Top, Front Section Only	\$726	\$1,180				6	23
1958	PC7504	Plastic Window Section Only for 7504 Top	\$323	\$469				3	
1959-60	7505	Chevrolet Impala Top, Front Serction Only	\$655	\$1,221				6	23
1959-60	PC7505	Plastic Window Section Only for 7505 Top	\$312	\$459				3	
1961-64	7506	Chevrolet Impala Top, Front Section Only	\$655	\$1,221				6	25
1961-64	PC7506	Plastic Window Section Only for 7506 Top	\$308	\$459				3	
1961-64	GL402	Non Heated Glass Window Section Only for 7506 Top. See V	\$737	\$933				3	
1962-63	7301	Chevy II/Nova Top, Front Section Only	\$644	\$1,221				6	21.75
1962-63	PC7301	Plastic Window Section Only for 7301 Top	\$308	\$456				3	
1964-65	7302	Chevelle/Malibu Top, Front Section Only	\$627	\$1,221				6	20.5
1964-65	PC7302	Plastic Window for 7302 Top	\$308	\$456				3	
1966-67	7303	Chevelle/Malibu Top, Front Section Only	\$611	\$1,180				6	22
1966-67	PC7303	Plastic Window Section Only for 7303 Top	\$308	\$456				3	
1962-67	GL401	Non Heated Glass Window Section Only for 7301,7302,7303	\$746	\$933				3	
1965-72	PD6572	Original Style Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).					\$427		
1966-97	CBL7303	Side Tension Cables for 7303 Top					\$155		
1962-64	7101	Corvair/Monza Top, Front Section Only	\$616	\$1,056				6	22.5
1962-64	PC7101	Plastic Window Section Only for 7101 Top	\$284	\$430				3	
1965-69	7102	Corvair/ Monza Top, Front Section Only	\$616	\$1,056				6	21.75
1965-69	PC7102	Plastic Window Section Only for 7102 Top	\$284	\$430				3	
1965-70	7507PC	Impala/Caprice Top, Combo Front & Plastic Window w/Zi	\$880	\$1,437				8	27.5
1965-70	7507T5	Impala/Caprice Top, Combo Front & Non Heated Glass Wind	\$1,204	\$1,729				8	27.5
1965-70	7507T7	Impala/Caprice Top, Combo Front & Non Heated Glass Wind	\$1,204	\$1,729				8	27.5
1965-70	7507	Impala/Caprice Top, Front Section Only	\$627	\$1,180				6	27.5
1965-70	PC7507	Plastic Window Section Only for 7507 Top	\$329	\$476				3	
1965-70	TN465	Non-Heated Glass Window Section Only w/Zipper for 7507 to	\$706	\$852				3	
1965-70	TN467	Non-Heated Glass Window Section Only, no Zipper for 7507	\$694	\$841				3	
1965-70	PD6572	Original Style Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).					\$427		
1965-70	CBL7507	Side Tension Cables for 7507 Top					\$155		
<b>YR</b>	<b>PART NO.</b>	<b>"SCISSOR TOP"</b>	<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1971-76	7509PC	Impala/Caprice Top Combo Front & Plastic Window Sections	\$924	\$1,509				10	
1971-76	7509TN	Impala/Caprice Top, Combo Fnt & Non Htd Glass Wndw. Ret	\$1,161	\$1,729				10	





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1971-76	7509HD	Impala/Caprice	Top, Combo Front & Htd Glass Wndw. Reuse	\$1,409	\$2,015				10
1971-76	7509	Impala/Caprice	Top, Front Section Only	\$611	\$1,098				7
1971-76	TN409	Non-Heated	Glass Window Section Only for 7509. Reuse wnc	\$706	\$850				3
1971-76	HD409	Heated Glass	Window Section Only for 7509 Top. Reuse wnc	\$982	\$1,128				3
1971-76	PC7509	Plastic Window	Section Only for 7509 Top	\$399	\$545				3
1971	CBL750	GM Scissor Top	Side Tension Cables						\$237
1972-76	CBL7509	GM Scissor Top	Side Tension Cables						\$208
1971-76	WB7509	Well Liner for 7509 Top							\$381
<b>YR</b>	<b>PART NO.</b>	<b>CHEVELLE/MALIBU</b>		<b>KV</b>	<b>SF</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1968-72	7304PC	Chevelle/Malibu	Top, Combo Front & Plastic Window Section	\$777	\$1,343			8	Fixed
1968-72	7304APC	Chevelle/Malibu	Top, Combo Front & Plastic Window Section	\$794	\$1,360			8	20.75
1968-72	7304TN	Chevelle/Malibu	Top, Combo Front & Non Htd Glass Windo	\$1,161	\$1,770			8	Fixed
1968-72	7304ATN	Chevelle/Malibu	Top, Combo Fnt & Non Htd Glass Wndw Sec	\$1,230	\$1,839			8	20.75
1968-72	7304	Chevelle/Malibu	Top, Front Section Only.	\$591	\$1,098			6	Fixed
1968-72	7304A	Chevelle/Malibu	Top, Front Section Only, Floating Bow	\$644	\$1,180			6	20.75
1968-72	PC7304	Plastic Window	Section Only for 7304 and 7304A Tops	\$262	\$408			3	
1968-72	TN404	Non-Heated	Glass Window for 7304 and 7304A Tops	\$685	\$831			3	
1968-72	WB7304	Well Liner for 7304 and 7304A Tops							\$343
1968-72	PD6572	Original Style	Tapered Top Pads for GM Full & *Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).						\$427
1968-72	CBL7304	Side Tension Cables for 7304 and 7304A Tops							\$155
<b>YR</b>	<b>PART NO.</b>	<b>CAMARO</b>		<b>KV</b>	<b>SF</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1967-70	7201PC	Camaro/Firebird	Top, Combo Fnt & Plastic Wndw Sections,	\$733	\$1,301			8	22.5
1967-70	7201ZPC	Camaro/Firebird	Top, Combo Fnt & Plastic Wndw Sections,	\$777	\$1,345			8	22.5
1967-70	7202GL	Camaro/Firebird	Top, Combo Fnt & Folding Non Htd Wndw ,w	\$1,131	\$1,689			8	22.5
1967-70			Deep well liner (WB7202) is required.						
1967-70	7201	Camaro/Firebird	Top, Front Section Only for 7201 top only	\$591	\$1,098			6	22.5
1967-70	7202	Camaro/Firebird	Top, Front Section Only for 7202 top only	\$591	\$1,098			6	22.5
1967-70	PC7201	Plastic Window	Section Only for 7201 top - No Zipper	\$266	\$412			3	
1967-70	PC7201Z	Plastic Window	Section Only for 7201 top - w/Zipper	\$284	\$430			3	
1967-70	GL304	Non Heated	Folding Glass Window Section Only for 7202 Top	\$689	\$850			3	
			Deep well liner (WB7202)required						
1967-70	WB7202	Deep Well Liner	required for 67-70 Camaro/Firebird w/GL304 glass						\$350
1967-70	CBL721	Camaro/Firebird	Side Tension Cables for 7201/7202 Tops						\$184
1987-88**	7203	Camaro/Firebird	Top w/ Plastic Window See Web or Catalo	\$697	\$1,061			6	
1988-91**	7204	Camaro/Firebird	Top w/ Plastic Window See Web or Catalo	\$697	\$1,061			6	
1990-92**	7205	Camaro/Firebird	Top w/ Plastic Window See Web or Cata	\$697	\$1,061			6	
1990-93**	7206	Camaro/Firebird	Top w/ Plastic Window See Web or Catalo	\$704	\$1,085			6	
			**Measurement system is approximate, and based on OEM top. This item is not guaranteed to fit Carefully compare our top to the old one BEFORE installing. This item is not returnable if installation has started.						
1993	HL972	Camaro/Firebird	Headliner						\$649
1987-93	CBL723	Camaro/Firebird	Side Tension Cables for 7203/7204/7205/7206 Tops						\$155
<b>YR</b>	<b>PART NO.</b>	<b>CAMARO</b>		<b>KV</b>	<b>AT</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
*1994-02	7210HD	Camaro/Firebird	Top, Combo Front & Heated Glass Window	\$1,131	\$1,230	\$1,454		8	23.25
*1994-02	7210	Camaro/Firebird	Top, Front Section Only. No seam at rear bo	\$655	\$709	\$946		6	23.25
			*Rear bow tack-strip (not included) is required for 1994 models. Available at N/C upon request						
1994-02	HD720	Camaro/Firebird	Heated Glass Window Section Only for 7	\$660	\$699	\$808		3	
1994-02	HL7210	Camaro/Firebird	Headliner						\$559
1994-02	CBL7210	23" OAL	Side Tension Cables for Camaro Top						\$155
1994-02	CBL7210A	29" OAL	Side Tension Cables for Camaro Top						\$155
<b>YR</b>	<b>PART NO.</b>	<b>CAVALIER/SUNFIRE</b>		<b>KV</b>	<b>SF</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1983-87	7310PC	Cavalier/Sunbird	Top, Combo Front & Plastic Window Ser	\$748	\$1,301			8	21.5
1983-87	7310	Cavalier/Sunbird	Top, Front Section Only	\$532	\$1,016			6	21.5
1983-87	PC7310	Plastic Window	Section Only for 7310 Top. Exposed color trin	\$335	\$481			3	
1983-87	CBL7310	Cavalier/Sunbird	Side Tension Cables						\$155
1983-87	CBL731R	Cavalier/Sunbird	Side Rear Flap Cables						\$155
1988-92*	7311PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw Sec. **See	\$704	\$1,262			8	26.25
1988-92*	7311	Cavalier/Sunbird	Top, Fnt Section Only. Uses wire-on at rear.	\$532	\$1,056			6	26.25
1988-92*	PC7311	Plastic Window	Section Only for 7311 Top. No exposed color	\$284	\$430			3	
1988-92	CBL7311	Cavalier/Sunbird	Side Tension Cables						\$155
1988-92	CBL731R	Cavalier/Sunbird	Side Rear Flap Cables						\$155



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1992-93*	7312PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw Sections. *	\$806	\$1,407			8	27	
1992-93*	7312TN	Cavalier/Sunbird	Top, Combo Fnt & Non Htd Glass Wndw.*Si	\$969	\$1,115			8	27	
1992-93*	7312HD	Cavalier/Sunbird	Top, Combo Fnt & Htd Glass Wndw. *See C	\$1,058	\$1,496			8	27	
1992-93*	7312	Cavalier/Sunbird	Top,Front Section Only.	\$532	\$1,016			6	27	
		Header not bound	No wire-on *See Catalog/Web							
1992-93*	TN412	Non-Heated	Glass Window Section Only for 7312 and 7313 T	\$558	\$706			3		
1992-93*	HD412	Heated Glass	Window Section for 7312 and 7313 Top	\$660	\$828			3		
1992-93*	PC7312	Plastic Window	Section Only for 7312, 7313 Top. Exposed Cc	\$360	\$506			3		
1992-94	CBL731	Cavalier/Sunbird	Side Tension Cables				\$155			
1992-93	CBL731R	Cavalier/Sunbird	Rear Flap Cables				\$155			
1993½-94*	7313PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw Sections. *	\$704	\$1,262			8	27	
1993½-94*	7313TN	Cavalier/Sunbird	Top, Combo Fnt & Non-Htd Glass Wndw. *S	\$941	\$1,524			8	27	
1993½-94*	7313HD	Cavalier/Sunbird	Top, Combo Fnt & Htd Glass Wndw. *See C	\$1,058	\$1,597			8	27	
1993½-94*	7313	Cavalier/Sunbird	Top, Fnt Section Only.	\$532	\$1,056			6	27	
		Binding/pocket	at header. *See Catalog/Web							
1993½-94*	TN412	Non-Heated	Glass Window Section Only for 7312 and 7313 T	\$558	\$706			3		
1993½-94*	HD412	Heated Glass	Window Section Only for 7312 and 7313 Top	\$660	\$828			3		
1993½-94*	PC7312	Plastic Window	Section Only for 7312, 7313 Top. Exposed Cc	\$360	\$506			3		
1992-1994	CBL731	Cavalier/Sunbird	Side Tension Cables				\$155			
1993½-94*	CBL731R	Cavalier/Sunbird	Rear Flap Cables				\$155			
1995-98	7316PC	Cavalier/Sunfire	Top, Combo Fnt & Plastic Wndw Sections,	\$777	\$1,301			8	27.5	
1995-98	7316TN	Cavalier/Sunfire	Top, Combo Fnt & Non Htd Glass Wndw Sec	\$941	\$1,526			8	27.5	
1995-98	7316HD	Cavalier/Sunfire	Top, Combo Fnt & Htd Glass Wndw Sections	\$1,013	\$1,600			8	27.5	
1995-98	7316	Cavalier/Sunfire	Top, Front Section Only, w/Deck Seams.	\$532	\$1,056			6	27.5	
1995-00	TN416	Non-Heated	Glass Window Section Only for 7316, 7317 Top	\$558	\$706			3		
1995-00	HD416	Heated Glass	Window Section Only for 7316, 7317 Top	\$660	\$828			3		
1995-00	PC7316	Plastic Window	Section Only for 7316, 7317 Top	\$360	\$506			3		
<b>YR</b>	<b>PART NO.</b>	<b>1998-00 Cavalier/Sunfire</b>			<b>SS</b>	<b>AT</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1998½-00	7317PC	Cavalier/Sunfire	Top, Combo Front & Plastic Wndw Sections.	\$792	\$859	\$1,301		8	27.5	
1998½-00	7317TN	Cavalier/Sunfire	Top, Combo Fnt & Non Htd Wndw Sections.	\$941	\$1,021	\$1,526		8	27.5	
1998½-00	7317HD	Cavalier/Sunfire	Top, Combo Fnt & Htd Wndw Sections. No C	\$969	\$1,053	\$1,600		8	27.5	
1998½-00	7317	Cavalier/Sunfire	Top, Front Section Only, No deck seams.	\$541	\$584	\$1,056		6	27.5	
1995-00	HL731	Cavalier/Sunfire	Headliner				\$396			
1995-98	CBL7316	Cavalier/Sunfire	Side Tension Cables				\$184			
1999-00	CBL7317	Cavalier/Sunfire	Side Tension Cables				\$184			
<b>YR</b>	<b>PART NO.</b>	<b>CELEBRITY</b>			<b>KV</b>	<b>SF</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1984-86	7315	Celebrity, Hess	& Eisenhardt Top, Front Section Only	\$697	\$1,180			6	18.5	
1984-86	PC7315	Plastic Window	Section Only for 7315 Top	\$360	\$511			3		
<b>YR</b>	<b>PART NO.</b>	<b>CORVETTE</b>			<b>KV</b>	<b>AT</b>	<b>ST</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1953-55	2050S	Corvette Top,	Sewn Plastic Window	\$726	\$848	\$1,180		5.5	15.75	
1956-58	2051††	Corvette Top,	Heat-sealed Plastic Window	\$631	\$733	\$1,140		5.5	15.5	
1956-58	2051S††	Corvette Top,	Sewn Plastic Window	\$655	\$762	\$1,140		5.5	15.5	
1959-60	2052W††	Corvette Top,	Reverse Heat-sealed Plastic Window	\$631	\$733	\$1,098		5.5	15.75	
1961-62	2053W††	Corvette Top,	Reverse Heat-sealed Plastic Window	\$627	\$677	\$1,098		5.5	15.5	
1956-62	PD851	1956-62	Corvette Top Pads for 2051, 2052W, 2053W				\$297			
1963-67	2054W††	Corvette Top,	Reverse Heat-sealed Plastic Window	\$627	\$677	\$1,056		5.5	18.5	
1963-67	PD854	1963-67	Corvette Original Style Top Pads (4 pc)				\$297			
1968-75	2055W††	Corvette Top,	Reverse Heat-sealed Plastic Window	\$627	\$677	\$1,056		5.5	14.5	
1968-75	PD855	1968-75	Corvette Original Style Top Pads				\$297			
1968-75	CBL2055	1968-75	Corvette Side Tension Cables				\$184			

†† For original style Warning Tag specify with "T" (e.g. 2052WT) when ordering, and add \$20.00 to retail.

YR	PART NO.	CORVETTE C4			KV	AT	ST	MISC.	HRS.	B/H
1986-93	2056WS	Corvette C4 Top with reverse	sealed and stitched plastic winc	\$675	\$730	\$996		7	16.5	
1986-93	HL2056	Corvette	Headliner				\$467			
1986-93	CBL2056	1986-93	Corvette Side Tension Cables				\$155			
1994-96	2057	Corvette C4 Top	with Heated Glass. Retrofits 1986-93 with us	\$1,059	\$1,245	\$1,305		7		
		KT2057 conversion kit. Wiring	for window defroster Not Supplied.							
1994-96	2057T	Corvette C4 Top	with Non-Original, Non-Heated Glass.	\$974	\$1,140	\$1,229		7		
		Retrofits 1986-93 with use of	KT2057 conversion kit.							



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1994-96	KT2057	Conversion Kit	required before installing 1994-96 top on 1986-93 Corvette. Wiring for window defroster Not Supplied.								\$410	
<b>YR</b>	<b>PART NO.</b>	<b>Corvette C5</b>	<b>PERMALOK Bonded Window</b>	<b>SS/AT</b>	<b>ST</b>	<b>TW</b>	<b>TWR</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1998-04	2058	Corvette C5	Top, with Heated Glass	\$1,044	\$1,245	\$1,379	\$1,517		7			
1998-99	HL957	1998-99	Corvette Headliner					\$467				
2000-04	HL958	2000-04	Corvette Headliner					\$467				
1998-04	CBL2058	1998-04	Corvette Side Tension Cables					\$198				
<b>YR</b>	<b>PART NO.</b>	<b>Corvette C6</b>		<b>SS/AT</b>	<b>ST</b>	<b>TWR</b>	<b>A5</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
2005-12	2059	Corvette C6 Top	with Heated Glass	\$1,180	\$1,440	\$1,584	\$1,816		6			
<b>YR</b>	<b>PART NO.</b>	<b>CHRYSLER</b>		<b>KV/CH</b>	<b>SF</b>				<b>HRS.</b>	<b>B/H</b>		
1963-64	5505	Chrysler	Newport, 300 Top, Front Section Only	\$749	\$1,221				6	30.25		
1963-64	PC5505	Plastic Window	Section Only for 5505 Top	\$312	\$459				3			
1965-66	5506	Newport, 300	Top, Front Section Only	\$749	\$1,301				6	27.5		
1965-66	PC5506	Plastic Window	Section Only for 5506 Top	\$323	\$469				3			
1967-68	5508	Newport, 300/Polara/ Fury	Top, Front Section Only	\$749	\$1,221				6	29.5		
1967-68	PC5508	Plastic Window	Section Only for 5508 Top	\$323	\$469				3			
1967-68	TN151	Non-Heated	Glass Window Section Only for 5508 Top	\$819	\$963				3			
1969-70	5510	Newport/300	Top, Front Section Only	\$749	\$1,221				6	33.25		
1969-70	PC5510	Plastic Window	Section Only for 5510 Top	\$404	\$550				3			
1969-70	TN153	Non-Heated	Glass Window Section Only for 5510 Top	\$801	\$947				3			
<b>YR</b>	<b>PART NO.</b>	<b>LEBARON</b>		<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1982-83	5401	Chrysler	LeBaron Top, Front Section Only	\$659	\$1,180				6	24.5		
1982-83	PC5401	Plastic Window	Section Only for 5401 Top	\$360	\$506				3			
1982-83	TN100	Non-Original	Folding, Non-Heated Glass Window Section Onl	\$631	\$777				3			
1982-83	PD801	1982-83 LeBaron	Top Pads					\$278				
1982-83	CBL5401	Side Tension	Cables for 5401 Top					\$155				
1984-86	5402	Chrysler	LeBaron Top, Front Section Only	\$558	\$1,016				6	22.75		
1984-86	PD802	1984-86 LeBaron	Top Pads No Qtr Pads.					\$370				
1984-86	PD802Q	1984-86 LeBaron	Top Pad and Qtr Pads					\$432				
1984-86	CBL5402	Side Tension	Cables for 5402 Top					\$155				
1984-86	TN102	Non-Heated	Glass Window Section Only for 5402 Top	\$558	\$706				3			
1984-86	PC5402	Plastic Window	Section Only for 5402 Top	\$346	\$492				3			
<b>YR</b>	<b>PART NO.</b>	<b>LEBARON</b>		<b>KV/SS</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1987-95	5404P3	Chrysler	LeBaron Top & Plastic Window with Zipper, No Wire	\$806	\$1,225				8.5	22.25		
1987-95	5404P4	Chrysler	LeBaron Top & Plastic Window, No Zipper, No Wire-	\$806	\$1,225				8.5	22.25		
1987-95	5404T3	Chrysler	LeBaron Top & Non-Heated Glass with Zipper, No V	\$941	\$1,482				8.5	22.25		
1987-95	5404T4	Chrysler	LeBaron Top & Non-Heated Glass, No Zipper, No W	\$911	\$1,360				8.5	22.25		
1987-95	5404H3	Chrysler	LeBaron Top & Heated Glass with Zipper, No Wire-C	\$1,181	\$1,645				8.5	22.25		
1987-95	5404H4	Chrysler	LeBaron Top & Heated Glass, No Zipper, No Wire-C	\$1,087	\$1,552				8.5	22.25		
1987-95	5404	Chrysler	LeBaron Top, Front Section Only, No Wire-On	\$558	\$1,016				6.5	22.25		
1987-95	HD103	Heated Glass	Window Section Only, with Zipper, for 5404	\$746	\$892				3			
1987-95	HD104	Heated Glass	Window Section Only, No Zipper, for 5404	\$698	\$845				3			
1987-95	TN103	Non-Orig.	Non-Heated Glass Window Section Only, w/Zipper,	\$548	\$689				3			
1987-95	TN104	Non-Orig.	Non-Heated Glass Window Section Only, No Zippe	\$530	\$676				3			
1987-95	PC5403	Non-Original	Plastic Window Section Only, with Zipper for 540	\$360	\$506				3			
1987-95	PC5404	Non-Original	Plastic Window Section Only, No Zipper for 540	\$344	\$490				3			
1987-89	HL967	Chrysler	LeBaron Headliner					\$771				
1990-94	HL968	Chrysler	LeBaron Headliner					\$771				
1995	HL969	Chrysler	LeBaron Headliner					\$771				
1987-91	CBL5403	Chrysler	LeBaron Side Tension Cables					\$155				
1992-95	CBL5404	Chrysler	LeBaron Side Tension Cables					\$155				
1987-95	PD5404	Buckram rubber	to reinforce 87-95 LeBaron top pads					\$121				
<b>YR</b>	<b>PART NO.</b>	<b>SEBRING (STRATUS EUROPE)</b>	<b>PERMALOK Bonded Windc</b>	<b>SS</b>	<b>AT</b>	<b>LM</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1996-00	5411HD	Sebring Top,	Combo Front & Heated Glass Window Section	\$954	\$1,037	\$1,245			7.5	26.25		
2001-06	5412HD	Sebring Top,	Combo Front & Heated Glass Window Section	\$954	\$1,037	\$1,245			7.5	26.25		
1996-00	5411	Sebring Top	Only, with Extrusions, Rain Guards	\$541	\$584	\$933			5.5	26.25		
2001-06	5412	Sebring Top	Only, with Extrusions, Rain Guards	\$541	\$584	\$933			5.5	26.25		
1996-06	HD105	Heated Glass	for 5411, 5412 with Extrusions	\$672	\$728	\$708			3			
1996-06	PC5410	Non-Original	Plastic Window for 5411, 5412	\$344	\$372	\$469			3			
1996-06	CBL541	Chrysler	Sebring Side Tension Cables					\$140				
1996-99	HL970	Sebring	Headliner					\$485				





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



YR	PART NO.	DESCRIPTION	SS	AT	TWR	MISC.	HRS.	B/H
2000-06	HL971	Sebring Headliner				\$485		
2008-13	5413	2008-10 Sebring and 2011-13 Chrysler 200 Top with original extrusions and retainers. Reuse factory rear glass.	\$613	\$662	\$1,083		6	
2004-08	5420	PT Cruiser Top with Heated Rear Glass	\$2,303	\$2,486			10	
1977-79	2525R	Clenet 1 Series Roadster Top w/1 Plastic Wndw;Hand Rolled	\$850	\$1,787	\$1,343		5	
1964-68	2512	Cobra AC Bristol Top w/plastic window	\$982	\$1,335	\$1,583		6	
	1511	1964½ -66½ Cobra Tonneau, Short	\$612	\$934	\$1,090		3	
	1512	1964-68 Cobra AC Bristol Tonneau	\$625	\$948	\$1,106		3	
Mid-1965	2120	Datsun Fairlady 1200, 1500 Top	\$748	\$1,180			6	
	1120	1964-65 Datsun Fairlady 1200, 1500 Tonneau	\$625	\$1,146			3	
1965-67½	2121	Datsun 1600, 2000 Top	\$748	\$1,180			6	
	1121	1965-67½ Datsun 1600, 2000 Tonneau	\$625	\$1,146			3	
1967½	2121A	Datsun 1600, 2000 Top	\$748	\$1,180			6	
	1121H	1967½ Datsun 1600,2000 Tonneau cover, with headrest pocket	\$625	\$1,146			3	
1968-69	2122	Datsun 1600, 2000 Top	\$748	\$1,180			6	
	1122H	1968-69 Datsun 1600, 2000 Tonneau cover, with headrest pocket	\$625	\$1,146			3	
	B1122	1968-69 Datsun 1600, 2000 Top Boot	\$608	\$1,077			1	
1968½-71	2123	Datsun 1600, 2000 Top	\$748	\$1,180			6	
	1123H	1970-71 Datsun 1600, 2000 Tonneau, with headrest pockets	\$641	\$1,187			3	
1963-64	5101	Dodge Dart Top, Front Section Only	\$704	\$1,221			7	24.5
1963-64	PC5101	Plastic Window Section Only for 5101 Top	\$330	\$478			3	
1965-66	5102	Dodge Dart Top, Front Section Only	\$671	\$1,098			7	24.5
1965-66	PC5102	Plastic Window Section Only for 5102 Top	\$323	\$469			3	
1965-66	5506	Polaris Top, Front Section Only	\$749	\$1,301			7	27.5
1965-66	PC5506	Plastic Window Section Only for 5506 Top	\$323	\$469			3	
1966	5507	Coronet Top, Front Section Only	\$749	\$1,221			7	27
1966	PC5507	Plastic Window Section Only for 5507 Top	\$323	\$469			3	
1967-68	5508	Polaris Top, Front Section Only	\$749	\$1,221			7	29.5
1967-68	PC5508	Plastic Window Section Only for 5508 Top	\$323	\$511			3	
1967-68	TN151	Non-Heated Glass Window Section Only for 5508 Top	\$819	\$963			2	
1967	5103	Dodge Dart Top, Front Section Only	\$697	\$1,180			7	24.5
1968-70	5104	Dodge Dart Top, Front Section Only	\$704	\$1,221			7	
1967-68	PC5103	Plastic Window Section Only for 5103 and 5104 Top	\$330	\$478			3	
1967-68	5509	Coronet Top, Front Section Only	\$749	\$1,221			7	23.25
1967-68	PC5509	Plastic Window Section Only for 5509 Top	\$404	\$550			3	
1967-68	TN152	Non-Heated Glass Window Section Only for 5509 Top	\$855	\$1,003			3	
1970-71	5302	Challenger Top, Front Section Only	\$704	\$1,221			7	22.5
1970-71	PC5302	Plastic Window Section Only for 5302 Top	\$335	\$478			3	
1970-71	TN132	Non-Heated Glass Window Section Only for 5302 Top	\$737	\$884			3	
1969-70	5510	Polaris Top, Front Section Only	\$749	\$1,221			7	33.25
1969-70	PC5510	Plastic Window Section Only for 5510 Top	\$404	\$550			3	
1969-70	TN153	Non-Heated Glass Window Section Only for 5510 Top	\$801	\$947			3	
1982-83	5401	Dodge 400 Top, Front Section Only	\$659	\$1,180			7	24.5
1982-83	PC5401	Plastic Window Section Only for 5401 Top	\$360	\$506			3	
1982-83	TN100	Non-Original Non-Htd Folding Glass Wndw Section Only, for 5401 Top	\$631	\$777			3	
1984-86	5402	Dodge 600/600ES Top, Front Section Only	\$558	\$1,016			7	22.75
1984-86	TN102	Non-Heated Glass Window Section Only for 5402 Top	\$558	\$706			3	
1984-86	PC5402	Plastic Window Section Only for 5402 Top	\$346	\$492			3	
1984-86	CBL5402	Side Tension Cables for 5402 Top				\$155		
1991-93	5000PC	Dodge Shadow Top (Wide Deck) w/Plastic Window	\$850	\$1,423			8	19
1991-93	5000APC	Dodge Shadow Top (Narrow Deck) w/Plastic Window	\$850	\$1,423			8	19
1991-93	5000	Dodge Shadow, Top Only, Wide Deck	\$607	\$1,056			6	19
1991-93	5000A	Dodge Shadow, Top Only, Narrow Deck	\$607	\$1,056			6	19
1991-93	PC5000	Plastic Window for 5000 and 5000A	\$360	\$463			3	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



YR	PART NO.	FERRARI	TW	GR		HRS.	B/H
1991-93	CBL5000	Dodge Shadow Side Tension Cables				\$180	
1967	2799RV	Ferrari 330 GTS Top	\$1,709	\$1,888		8	
1966-67	2800RV	Ferrari 275-330	\$1,871	\$2,089		8	
1971-74	2801RV	Ferrari 365 GTB-4 Top	\$1,871	\$2,089		8	
1984-94	2802R	Ferrari Mondial Cabriolet Top - All Years	\$2,089	\$2,213		8	
YR	PART NO.	FIAT	KV	ST	MISC.	HRS.	B/H
1959	2029	Fiat 1100 Top w/plastic window	\$704	\$933		5	
1960-63	2030	Fiat 1200 Top w/plastic window	\$704	\$1,221		5	
1964-66	2030A	Fiat 1500 Top w/plastic window	\$704	\$1,221		5	
1967-73	2031	Fiat 850 Top w/plastic window	\$704	\$1,098		5	
1966-79	2032**	Fiat 124-CS1, 1600-2000 Top **See Web or Catalog Diagram	\$704	\$1,098		5	
1966-79	1032	Fiat 124-CS1, 1600-2000 Tonneau	\$670	\$1,080		3	
1970-79	1032H	Fiat 124-CS1 Tonneau, with Headrest Pockets	\$728	\$1,138		3	
1979-85	2032A**	Fiat 124-CS2, 2000 Top **See Web or Catalog Diagram	\$704	\$974		5	
1979-85	1032A	Fiat 124-CS2 Tonneau	\$714	\$1,125		3	
1968-75	2070	Fiat Siata, Siata Spring Top	\$704	\$1,343		5	
1971-94	CBLRS	Fiat & Alfa Universal side tension cables				\$155	
YR	PART NO.	BARCETTA	KV	ST	TW	HRS.	B/H
1995-05	2071	Barchetta Top with Plastic Window, No Zipper	\$675	\$1,200	\$1,343	8	
YR	PART NO.	FORD	KV	SF	MISC.	HRS.	B/H
1961-62	6503	Galaxie Top, Front Section Only	\$713	\$1,180		6	26.75
1961-62	PC6503	Plastic Window Section Only for 6503 Top	\$312	\$511		3	
1963	6504	Galaxie Top, Front Section Only	\$713	\$1,180		6	23.5
1963	PC6504	Plastic Window Section Only for 6504 Top	\$329	\$476		3	
1963-65	6101	Falcon/Sprint Top, Front Section Only	\$671	\$1,140		6	23.5
1963-65	PC6101	Plastic Window Section Only for 6101 Top	\$329	\$476		3	
1964	6505	Galaxie XL Top, Front Section Only	\$713	\$1,180		6	23
1964	PC6505	Plastic Window Section Only for 6505 Top	\$308	\$456		3	
1964	TN337	Non-Heated Glass Window Section Only for 6505 Top	\$698	\$845		3	
1965-66	6506	Galaxie XL Top, Front Section Only	\$713	\$1,180		6	27
1965-66	TN338	Non-Heated Glass Window for 6506 Top	\$737	\$884		3	
1965-66	CBL6506	Side Tension Cables for 6506 and 6507 Top				\$155	
1967-68	6507	Galaxie XL/LTD Top, Front Section Only	\$713	\$1,180		6	28
1965-66	PC6506	Plastic Window for 6506 and 6507 Top	\$308	\$456		3	
1967-68	TN339	Non-Heated Glass Window Section Only for 6507 Top	\$737	\$884		3	
1966-67	6301	Fairlane Top, Front Section Only	\$703	\$1,140		6	27
1966-67	PC6301	Plastic Window Section Only for 6301 Top	\$308	\$456		3	
1966-67	TN319	Non-Heated Glass Window Section for 6301 Top	\$729	\$875		3	
1968-71	6302	Fairlane/Torino Top, Front Section Only	\$703	\$1,140		6	27
1968-71	PC6302	Plastic Window Section Only for 6302 Top	\$308	\$456		3	
1968-71	TN320	Non-Heated Glass Window Section Only for 6302 Top	\$729	\$875		3	
1968-71	CBL6302	Side Tension Cables for 6302 Top				\$155	
1969-72	6508	Galaxie XL/LTD Top, Front Section Only	\$713	\$1,180		6	30
1969-72	PC6508	Plastic Window Section Only for 6508 Top	\$308	\$456		3	
1969-72	TN340	Non-Heated Glass Window Section Only for 6508 Top	\$737	\$884		3	
1969-72	CBL6508	Side Tension Cables for 6508 Top				\$155	
YR	PART NO.	1955-1966THUNDERBIRD	KV	ST	MISC.	HRS.	B/H
1955-56	2510	T-Bird Top, Front Section Only	\$631	\$1,054		6	18.5
1955-56	PC2510	Plastic Window Section Only for 2510 Top	\$411	\$557		3	
1955-56	1510	1955-56 T-Bird Tonneau	\$641	\$1,106		3.5	
1957	2511	T-Bird Top, Front Section Only	\$644	\$1,056		6	19.5
1957	PC2511	Plastic Window Section Only for 2511 Top	\$335	\$481		3	
1957	1510A	1957 T-Bird Tonneau	\$641	\$1,106		3.5	
1958-60	6401	T-Bird Top, Front Section Only	\$749	\$1,180		6	18.5
1958-60	PC6401	Plastic Window Section Only for 6401 Top	\$375	\$521		3	
1961-63	6402	T-Bird Top, Front Section Only	\$749	\$1,180		6	23.5
1961-63	PC6402	Plastic Window Section Only for 6402 Top	\$375	\$521		3	
1964-66	6403	T-Bird Top, Front Section Only	\$764	\$1,221		6	22.5
1964-66	PC6403	Plastic Window Section Only for 6403 Top	\$375	\$521		3	
1964-66	CBL6403	Side Tension Cables for 6403 Top				\$155	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



YR	PART NO.	2001-2005 THUNDERBIRD	ST	MISC.	HRS.	B/H			
2001-05	2514HD	Thunderbird Top, Combo Front & Heated Glass Window	\$1,318		10				
2001-05	2514C	Thunderbird Front Section Only, headliner not supplied	\$1,018		8				
2001-05	HD514	Heated Glass Window Section Only for 2514 Thunderbird Top	\$952		3				
YR	PART NO.	FORD MUSTANG 64 1/2 - 73	KV	SF	MISC.	HRS.	B/H		
1964½-66	6202PC	Mustang Top, Combo Front & Plastic Window Sections.	\$704	\$1,262		8	21		
1964½-66	6203GL	Mustang Top, Combo Front & Folding Glass Window Section: Deep Well Liner (WB6203) is required.	\$1,058	\$1,605		9			
1964½-66	6202	Mustang Top Front Section only. For use with Plastic Window	\$558	\$1,056		6	21		
1964½-66	6203	Mustang Top Front Section Only. For use with GL304 folding	\$575	\$1,073		6	21		
1964½-66	PC6202	Plastic Window Section Only for 6202 Top	\$271	\$418		3			
1964½-66	CBL6200	Side Tension Cables (pr) 28" OAL, attaches with studs			\$155				
1965-66	CBL6202	Side Tension Cables (pr) 28 1/4" OAL, attaches w/springs			\$155				
1967-68	6204PC	Mustang Top, Combo Front & Plastic Window Sections.	\$709	\$1,180		8	20.5		
1967-68	6204GL	Mustang Top, Combo Front & Folding Glass Window Section: Deep Well Liner (WB6203) is required	\$1,058	\$1,605		9	20.5		
1967-68	6204	Mustang Top Front Section Only.	\$558	\$1,056		6	20.5		
1967-68	PC6204	Plastic Window Section Only for 6204 and 6205 Tops	\$284	\$430		3			
1967-68	GL304	Folding Glass Window Section Only for 6204 Top. Deep Well Liner (WB6203) is required.	\$689	\$850		3			
1967-68	CBL6202	Mustang Side Tension Cables, 28 1/4" OAL, attaches w/springs			\$155				
1964-68	WB6203	Deep Well Liner required for 64½-68 Mustang using folding glass			\$350				
1969-70	6205PC	Mustang Top, Combo Front & Plastic Window Sections.	\$762	\$1,180		8	19.5		
1969-70	6205GL	Mustang/Cougar Top, Combo Front & Folding Glass Window Sections. Deep Well Liner (WB6205) is required	\$1,102	\$1,645		9	19.5		
1969-70	6205	Mustang Top, Front Section Only.	\$584	\$1,056		6	19.5		
1969-70	PC6204	Plastic Window Section Only for 6205 Top.	\$284	\$430		3			
1969-70	GL304	Folding Glass Wndw Sec Only for 6205 Top. Deep Well Liner	\$689	\$850		3			
1969-70	CBL6205	Mustang/Cougar Side Tension Cables 29" OAL.			\$155				
1969-70	WB6205	Deep Well Liner required for 1969-70 Mustang using folding glass			\$350				
1971-73	6206PC	Mustang Top, Combo Front & Plastic Window Sections.	\$733	\$1,150		8	25.25		
1971-73	6206TN	Mustang Top, Combo Front & Non-Heated Glass Window Section	\$1,102	\$1,524		8	25.25		
1971-73	6206	Mustang Top, Front Section Only.	\$584	\$1,180		6	25.25		
1971-73	PC6206	Plastic Window Section Only for 6206 Top.	\$299	\$445		3			
1971-73	TN306	Non-Heated Glass Window Section Only for 6206 Top.	\$660	\$808		3			
1971-73	CBL6206	Mustang/Cougar Side Tension Cables 24 1/2" OAL.			\$155				
YR	PART NO.	FORD MUSTANG 83-93	KV	SF	MISC.	HRS.	B/H		
1983-90	6208PC	Mustang Top, Combo Front & Non-Original Plastic Window Section	\$749	\$1,363		8	25.25		
1983-90	6208TN	Mustang Top, Combo Front & Non-Heated Glass Window Section	\$853	\$1,468		8	25.25		
1983-90	6208	Mustang Top, Front Section Only	\$518	\$974		6	25.25		
1983-90	TN307	Non-Heated Glass Window Section Only, with coil zipper for €	\$510	\$666		3			
1983-90	PC6207	Non-Orig. Plastic Window Section Only, with coil zipper for 62	\$344	\$490		3			
1983-90	PD827	Mustang Original Style Top & Qtr Pads			\$381				
1983-88	CBL6208	Mustang Side Tension Cables 34 1/2" OAL			\$155				
1989-90	CBL6208L	Mustang Side Tension Cables 35 1/2" OAL			\$155				
1991-92	6209PC	Mustang Top, Combo Fnt & Non-Orig. Plastic Wndw Sec. (W	\$749	\$1,421		8	26		
1991-92	6209TN	Mustang Top, Combo Front & Non-Heated Glass Window Section	\$861	\$1,468		8	26		
1993	6209T0	Mustang Top, Combo Front & Non-Heated Glass Window Section	\$897	\$1,482		8	26		
1991-93	6209	Mustang Top, Front Section Only.	\$518	\$1,016		6	26		
1991-93	PC6207	Non-orig. Plastic Wndw Section w/Velcro and coil zipper for	\$344	\$490		3			
1983-92	TN307	Non-Heated Glass Window Section Only, with coll zipper for €	\$510	\$666		3			
1993	TN310	Non-Htd Glass Wndw Sec w/velcro tabs & moldd zipper for 6:	\$514	\$676		3			
YR	PART NO.	MUSTANG 1994-2004 PERMALOK Bonded Window	SS	AT	SF	TW	MISC.	HRS.	B/H
1994-04	6213TN	Mustang Top, Combo Front & Non-Heated Glass Window Section	\$786	\$850	\$1,208	\$1,361		8	24.5
1994-04	6213HD	Mustang Top, Combo Front & Heated Glass Window Section:	\$922	\$1,000	\$1,401	\$1,640		8	24.5
1994-04	6213	Mustang Top, Front Section Only, 2 Listings w/seals	\$486	\$522	\$901	\$1,140		6	24.5
1994-04	TN311	Non-Heated Glass Window Section Only for 6213 Tops	\$500	\$539	\$628	\$628		3	
1994-04	HD311	Heated Glass Window Section Only for 6213 Tops	\$622	\$672	\$651	\$651		3	
1994-98	HL921	Mustang Headliner					\$485		
1999-04	HL922	Mustang Headliner					\$485		
1994-2/95	CBL6211	Mustang Side Tension Cables					\$140		



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



3/95-98	CBL6212	Mustang Side	Tension Cables							\$140		
1999-04	CBL6213	Mustang Side	Tension Cables							\$140		
1994-04	CBL621R	Mustang	(Quarter Flap Cables)							\$184		
<b>YR</b>	<b>PART NO.</b>	<b>MUSTANG</b>	<b>2005-ON</b>	<b>PERMALOK Bonded Window</b>	<b>SS</b>	<b>AT</b>	<b>ST</b>	<b>TWR</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>	
2005-08	6220	Mustang	One-Piece Top with Heated Glass		\$1,394	\$1,465	\$1,517	\$1,850		8	21.75	
2009-11	6221	Mustang	One-Piece Top with Heated Glass, w/Rain Guards		\$1,428	\$1,486	\$1,539	\$1,871		8	21.75	
2012-13	6223	Mustang	One-Piece Top with Heated Glass, w/Rain Guards		\$1,442	\$1,506	\$1,553	\$1,885		8	21.75	
2005-13	HL622	Mustang	Headliner							\$835		
2005-12	CBL622	Side Tension	Cables for Mustang							\$184		
<b>YR</b>	<b>PART NO.</b>	<b>FORD (EUROPE)</b>	<b>ESCORT</b>	<b>RC</b>					<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>	
1983-91	2550	Ford of Europe	Escort Top. Resuse original glass window		\$725						6	
1991-97	2551	Ford of Europe	Escort Top. Resuse original glass window		\$771						6	
1983-91	HL2550	1983-91 Ford of	Europe Escort Headliner							\$490		
1991-97	HL2551	1991-97 Ford of	Europe Escort Headliner							\$490		
<b>YR</b>	<b>PART NO.</b>	<b>GEO</b>	<b>METRO</b>	<b>KV</b>	<b>SF</b>				<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>	
1990-93	7330	Geo Metro, Top	- See Catalog/Web		\$753	\$1,180					6	
1990-93	CBL7330	Geo Metro Side	Tension Cables							\$184		
<b>YR</b>	<b>PART NO.</b>	<b>GEO / CHEVY TRACKER</b>		<b>CM</b>	<b>JP</b>	<b>SF</b>					<b>HRS.</b>	<b>B/H</b>
1989-94	7350	Tracker, Complete	Top		\$1,007	\$932	\$1,790				0.5	
1989-94	PC7350L	Replacement Rear	Plastic Window for OE Tops in Europe - Zipper Opens Left to Right.		\$338	\$330						
1989-94	PC7350R	Replacement Rear	Plastic Window for 7350 and USA OE Tops - Zipper Opens Right to Left.		\$338	\$330						
1995-98	7351	Tracker, Complete	Top		\$1,115	\$1,062	\$2,062				0.5	
1995-98	PC7351L	Replacement Rear	Plastic Window for 7351 Top, Zipper Opens Left to Right.		\$338	\$330						
1995-98	PC7351R	Replacement Rear	Plastic Window for OEM Tops in Europe, Zipper Opens Right to Left.		\$338	\$330						
1995-98	SC7351	Replacement Side	Curtains for Tracker		\$475	\$448	NA				NA	
<b>YR</b>	<b>PART NO.</b>	<b>HILLMAN MINX</b>		<b>CG</b>	<b>BS</b>						<b>HRS.</b>	<b>B/H</b>
1957-59	2602	Hillman Minx	Top w/plastic window		\$832	\$1,364					8	
1957-59	2602P	Hillman Minx	Top w/ plastic window, w/sewn-in pads		\$1,004	\$1,510					8	
1960-63	2603	Hillman Minx	Top w/plastic window		\$781	\$1,313					8	
1960-63	2603P	Hillman Minx	Top w/ plastic window, w/sewn-in pads		\$1,004	\$1,510					8	
1964-67	2604	Hillman Minx	Top w/plastic window		\$799	\$1,386					8	
<b>YR</b>	<b>PART NO.</b>	<b>HONDA</b>		<b>KV</b>							<b>HRS.</b>	<b>B/H</b>
1963-64	2529	Honda S500 Top	w/3 Plastic Windows		\$762						6	
1964-66	2530	S600 & 1966-67½	S800 Top w/3 Plastic Windows		\$762						6	
1964-66	2530Z	S600 & 66-67½	S800 Top w/3 Plastic Windows, Zipper		\$924						6	
1964-66	2532	Honda S600 Top	w/1 Plastic Window		\$748						6	
1966-67½	2530	Honda S800 & 1964-66	S600 Top w/3 Plastic Windows		\$762						6	
1967-70	2531	Honda S800 Top	w/plastic window. Fits Late 1967-70		\$762						6	
1967-70	2531Z	Honda S800 Top	w/3 plastic windows, Zipper. Fits Late 67-70		\$873						6	
<b>YR</b>	<b>PART NO.</b>	<b>BEAT</b>		<b>KV</b>	<b>RC</b>	<b>ST</b>					<b>HRS.</b>	<b>B/H</b>
1991-95	2533	Honda Beat Top	w/ Plastic Window		\$952	\$1,070	\$1,144				6	
1991-95	2534	Honda Beat Top	w/ Non Heated Glass Window		\$1,058	\$1,161	\$1,248				6	
<b>YR</b>	<b>PART NO.</b>	<b>S2000</b>		<b>AT</b>	<b>HV</b>	<b>ST</b>					<b>HRS.</b>	<b>B/H</b>
2000-01	2535	Honda S2000 Top	w/Plastic Window		\$1,056	\$1,119	\$1,264				8	
2000-01	2537	Honda S2000 Top	w/Non-Heated Glass (straps incl)		\$1,298	\$1,379	\$1,544				8	
2000-01	2538	Honda S2000 Top	w/Heated Glass (straps incl) no wiring		\$1,331	\$1,425	\$1,642				8	
2002-09	2540	Honda S2000 Top	w/Heated Glass		\$1,338	\$1,434	\$1,600				8	
<b>YR</b>	<b>PART NO.</b>	<b>ISUZU AMIGO</b>		<b>JD</b>							<b>HRS.</b>	<b>B/H</b>
1989-94	7370	Isuzu Amigo Top	w/plastic window		\$1,172						1	
<b>YR</b>	<b>PART NO.</b>	<b>JAGUAR</b>	<b>JAGUAR 1949-74</b>	<b>CG</b>	<b>EF</b>	<b>BS</b>	<b>ST</b>				<b>HRS.</b>	<b>B/H</b>
1949-51	*2412	Jaguar XK120	Roadster Top w/plastic window		\$762	\$826	\$1,094	\$1,221			8	
1949-51	*2412N	Jaguar XK120	Roadster Top w/o window (Blank)		\$762	\$826	\$1,080	\$1,221			8	
1949-50	*1410	Roadster XK-120	Long Tonneau		\$597	\$647	\$962	\$1,146			3	
1949-50	*1410A	Roadster XK-120	Short Tonneau		\$597	\$647	\$992	\$1,197			3	

\*\*Does Not fit XK120 Alloy model with 2 fasteners in L & R quarters.



Robbins Auto Tops Canadian Suggested Retail Price List  
Featuring Robbins complete selection of XT Budget Tops  
August 15, 2016



1952-57	2413	XK-120, XK-140	Roadster Top w/plastic window	\$762	\$826	\$1,114	\$1,246	8		
1952-57	2413N	XK-120, XK-140	Roadster Top w/o window (Blank)	\$762	\$826	\$1,114	\$1,246	8		
1952-57	2413Z	XK-120, XK-140	Roadster Top with 3 plastic windows, Brass	\$1,128	\$1,229	\$1,290	\$1,392	8		
1952-57	2413ZN	XK-120, XK-140	Roadster Top w/o windows	\$1,041	\$1,133	\$1,275	\$1,509	8		
1951-54	1411	XK-120 Roadster	Tonneau, Long	\$597	\$647	\$962	\$1,187	3		
1951-54	1411A	XK-120 Roadster	Tonneau, Short	\$597	\$647	\$992	\$1,187	3		
1955	1413	XK-140 Roadster	Tonneau, Long	\$612	\$664	\$962	\$1,187	3		
1956-57	1413A	XK-140 Roadster	Tonneau, Short	\$597	\$647	\$992	\$1,187	3		
1952-57	2414	XK-120, XK-140	Drophead Top w/plastic window	\$762	\$826	\$1,221	\$1,202	8		
1952-57	2414N	XK-120, XK-140	Drophead Top w/o window (Blank)	\$762	\$826	\$1,144	\$1,187	8		
1958-60	2415	XK-150 Roadster	Top w/plastic window	\$850	\$924	\$1,209	\$1,246	8		
1958-60	2415N	XK-150 Roadster	Top w/o window (Blank)	\$822	\$892	\$1,209	\$1,202	8		
1958-61	1415	XK-150 Roadster	Tonneau, Long	\$625	\$679	\$1,007	\$1,267	3		
1958-61	1415A	XK-150 Roadster	Tonneau, Short	\$612	\$664	\$992	\$1,228	3		
1958-60	2416	XK-150 Drophead	Top w/plastic window	\$850	\$924	\$1,301	\$1,261	8		
1958-60	2416N	XK-150 Drophead	Top w/o window (Blank)	\$822	\$892	\$1,246	\$1,217	8		
1961-71	2417	XK-E Roadster	& "E" Type Top w/ plastic window	\$650	\$703	\$933	\$1,016	5		
1961-71	2417Z	XK-E Roadster	& "E" Type Top w/ plastic window, Zipper	\$796	\$864	\$1,080	\$1,163	5		
1961-71	1417	1961-71 XK-E	Roadster & "E" Type tonneau cover	\$626	\$681	\$1,007	\$1,239	3		
1961-71	2417WS	Three Piece	Wood Tack Strip for XKE					\$529		
1972-74	2418	Jaguar	"E" Type - V12 Top w/plastic window	\$704	\$762	\$933	\$1,056	5		
1972-74	B1418	Jaguar	"E" Type Top Boot	\$684	\$745	\$1,110	\$1,309	1		
YR	PART NO.	1988 HESS & EISENHARDT		KV	EF	ST		HRS.	B/H	
1988	2419	Jaguar	Top w/o window, Hess & Eisenhardt	\$704	\$762	\$1,098		8		
1988	HD219	Refurbished	Glass Rear Window for 2419 Top	\$704	\$762	\$850		3		
		Customer Must Supply Original Glass, No Warranty								
1988	PC2419	Non-Original	Plastic Window for 2419 Top	\$490	\$532	\$638		3		
YR	PART NO.	1989-2006		AT	TW	GR	A5	MISC	HRS.	B/H
1989-95	2422R	XJS, XJR	Top w/o window, Fits to Factory Glass Window	\$1,151	\$1,228	\$1,390	NA		8	
1997-06	2423C	XK8, XKR	Top w/o window, Fits to Factory Glass Window	\$1,120	\$1,172	NA	\$1,335		8	
JAGUAR HEADLINERS										
1989-93	HL2422	XJS	Headliner					\$843		
1997-00	HL2423	XK8/XKR	Headliner					\$843		
2001-06	HL2424	XK8/XKR	Headliner					\$843		
YR	PART NO.	JENSEN		CG	BS	ST		HRS.	B/H	
1972-75	2440	Jensen Healey	Roadster Top w/plastic window	\$894	\$1,221	\$1,301		8		
1972-75	1440	1972-75 Jensen	Healey Roadster Tonneau	\$695	\$898	\$940		3		
1972-75	B1440	1972-75 Jensen	Healey Roadster Top Boot	\$595	\$842	\$885		2		
1974-76	2441	Jensen	Interceptor Top w/plastic window	\$1,363	\$2,111	\$2,213		8		
1974-76	2441R*	Jensen	Interceptor Top, w/plastic window, hand-rolled binding	\$1,554	\$2,198	\$2,359		8		
		*MUST SPECIFY GRAY OR TAN WINDOW LINING								
YR	PART NO.	KARMANN GHIA		KV	ST		MISC.	HRS.	B/H	
1958-66	2025	Karmann-Ghia	Top with plastic window	\$697	\$1,056			5		
1958-66	2025Z	Karmann-Ghia	Top with plastic window, Zipper	\$855	\$1,481			5		
1966-67	2025A	Karmann-Ghia	(CNV 141) Top with Plastic Window	\$712	\$974			6		
1967½-69	2024	Karmann-Ghia	(CNV 1411) Top with Plastic Window	\$712	\$933			6		
1969½-76	2024A	Karmann-Ghia	Top. Fits to original glass window.	\$712	\$1,056			6		
1954-79	CBLVWRS	Beetle, Karmann	Ghia, Rabbit, Cabriolet Side Cables					\$151		
1967-69	CBL2024R	Karmann Ghia	rear mounting cable for 2024/2024A (each)					\$115		
1967-69	CBL2024W	Karmann Ghia	rear window cable for 2024/2024A (each)					\$170		
YR	PART NO.	LANCIA		KV	ST			HRS.	B/H	
1979-81	2600R	Lancia Zagato	Top	\$762	\$1,379			4		
YR	PART NO.	LINCOLN		KV	EV	SF		HRS.	B/H	
1961-63	6602	Lincoln Continental	Top, Front Section Only	\$771	\$927	\$1,221		6	20.5	
1961-63	PC6602	Plastic Window	Section Only for 6602 Top	\$399	\$432	\$545		3		
1964-65	6603	Lincoln Continental	Top, Front Section Only	\$771	\$925	\$1,221		6	20.5	
1964-65	PC6603	Plastic Window	Section Only for 6603 Top	\$399	\$432	\$545		3		
1966-67	6604	Lincoln Continental	Top, Frnt Sec Only, Fits with Factory Glas	\$812	\$963	\$1,262		8		
YR	PART NO.	LOTUS		CG	BS	ST		HRS.	B/H	
1961-66	2505	Lotus Elan S-1,	1600 S-2 Roadster Top w/plastic window	\$792	\$1,172	\$1,407		5		
1961-66	1505	1961-66 Lotus	Elan S-1, 1600 S-2 Tonneau	\$743	\$1,271	\$1,403		3		





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1967-72	2506	Lotus Elan S-3, S-4 Drophead Top w/plastic window	\$939	\$1,392	\$1,525			5	
1967-72	B1506	1967-72 Lotus Elan S-3, S-4 Drophead Top Boot	\$682	\$1,077	\$1,239			2	
<b>YR</b>	<b>PART NO.</b>	<b>MASERATI</b>	<b>TW</b>	<b>GR</b>				<b>HRS.</b>	<b>B/H</b>
1986-89	2320R*	Maserati Bi-Turbo Top with Plastic Window	\$1,802	\$2,022				6	
		*MUST SPECIFY GRAY OR TAN WINDOW LINING							
1989-91	5400C	Chrysler, Maserati TC Top w/o window (Glass N/A)	\$1,632	\$1,998				8	
		<b>MAZDA</b>							
<b>YR</b>	<b>PART NO.</b>	<b>1990-05 MAZDA MIATA MX5 FACTORY STYLE TOPS</b>	<b>RC</b>	<b>AT</b>	<b>ST</b>			<b>HRS.</b>	<b>B/H</b>
		PLASTIC WINDOW							
1990-97	2900	Miata Top with Plastic Window, Zipper, Deck Seams, No Rain	\$937	\$1,020	\$1,340			5.5	
1990-97	2901	Miata Top with Plastic Window, Zipper, Deck seams, w/R	\$1,169	\$1,275	\$1,569			5	
		PERMALOK BONDED GLASS WINDOW							
1990-05	2958	Miata Top w/Non-Hted Glass, Deck Seams, No Zipper, No Rain	\$1,102	\$1,199	\$1,504			6	
1990-05	2959	Miata Top w/Non-Heated Glass, Deck Seams, No Zipper, w/R	\$1,353	\$1,475	\$1,586			5.5	
1990-05	2960	Miata Top w/Heated Glass, Deck Seams, No Zipper, No Rain	\$1,136	\$1,235	\$1,401			6	
1990-05	2961	Miata Top w/Heated Glass, Deck Seams, No Zipper, w/Rain	\$1,394	\$1,520	\$1,670			5.5	
1990-05	2964	Miata Top w/Non-Hted Glass, Deck Seams, w/Zipper, No Rain	\$1,179	\$1,282	\$1,433			6	
1990-05	2965	Miata Top w/Non-Heated Glass, Deck Seams, w/Zipper, w/R	\$1,401	\$1,527	\$1,662			5.5	
1990-05	2962	Miata Top w/Heated Glass, Deck Seams, w/Zipper, No Rain	\$1,171	\$1,276	\$1,459			6	
1990-05	2963	Miata Top w/Heated Glass, Deck Seams, w/Zipper, w/Rain	\$1,433	\$1,562	\$1,677			5.5	
<b>YR</b>	<b>PART NO.</b>	<b>1990-05 MAZDA MIATA MX5 BUDGET ONE PIECE TOPS</b>	<b>RC</b>	<b>AT</b>	<b>ST</b>			<b>HRS.</b>	<b>B/H</b>
		PLASTIC WINDOW							
1990-05	2904	Miata 1 Piece Top w/Plastic Window, No Deck Seams No	\$678	\$735	\$1,034			5.5	
1990-05	2905	Miata 1 Piece Top w/Plastic Window, No Deck Seams, w/Rai	\$814	\$884	\$1,169			5	
		PERMALOK BONDED GLASS WINDOW							
1990-05	2916	Miata 1 Piece Top w/Heated Glass, No Deck Seams, No	\$928	\$1,007	\$1,234			6	
1990-05	2917	Miata 1 Piece Top w/Heated Glass, No Deck Seams, w/R	\$1,146	\$1,247	\$1,453			5.5	
1990-05	2918	Miata 1 Piece Top w/ Non Hted Glass, No Deck Seams, N	\$894	\$971	\$1,194			6	
1990-05	2919	Miata 1 Piece Top w/Non Hted Glass, No Deck Seams,w/	\$1,113	\$1,211	\$1,412			5.5	
<b>YR</b>	<b>PART NO.</b>	<b>1990-05 MIATA, MX5 PARTS &amp; ACCESSORIES</b>	<b>RC</b>	<b>AT</b>	<b>ST</b>			<b>HRS.</b>	<b>B/H</b>
1990-97	2989Z	Replacement Front Section Only for 2900/2901 Tops	\$753	\$817	\$1,247			4	
1990-97	PC2900	Replacement Plastic Window Section Only for 1990-97 OEM	\$462	\$501	\$608				
1990-97	PC2900Z	Plastic Window Section Only for 2900/2901 Tops w/zipper	\$478	\$518	\$624			3	
1990-97	1900H	Plastic Window Top Tonneau Cover w/Headrest Pockets	\$801	\$873	\$1,345			1	
1990-97	1902H	Glass Window Top Tonneau Cover w/Headrest Pockets	\$801	\$873	\$1,345			1	
1990-97	B1900	Miata Boot Cover for Plastic Window Top	\$595	\$647	\$852			N/A	
1990-97	B1902	Miata Boot Cover for Glass Window Top	\$595	\$647	\$852			N/A	
1999-00	1904H	Miata Tonneau Cover with headrest pockets	\$801	\$873	\$1,345			1	
1999-05	B1904	Miata Boot Cover	\$595	\$647	\$852			N/A	
2001-03	1905H	Miata Tonneau Cover with headrest pockets Fits vehicles NOT equipped with windblocker thru 2005	\$801	\$873	\$1,345			1	
1990-05	29RR	Miata Rain Rail						\$286	1
1990-97	CBL2900	Miata Side Tension Cables						\$155	
1999-05	CBL2960	Miata Side Tension Cables						\$155	
<b>YR</b>	<b>PART NO.</b>	<b>2006-2013 MAZDA MIATA PERMALOK Bonded Window</b>	<b>RC</b>	<b>AT</b>	<b>ST</b>			<b>HRS.</b>	<b>B/H</b>
2006-13	2968	Miata Top w/ Heated Glass w/Low Profile Rainguards. Rainra	\$1,186	\$1,292	\$1,473			6.5	
<b>YR</b>	<b>PART NO.</b>	<b>MAZDA RX-7</b>	<b>KV</b>	<b>ST</b>				<b>HRS.</b>	<b>B/H</b>
1988-92	2931	RX-7 Top, Front & Rear Sections, w/Rain-guards. Reuse fact	\$1,482	\$2,245				6	
<b>YR</b>	<b>PART NO.</b>	<b>MERCEDES BENZ</b>	<b>ST</b>	<b>TW</b>	<b>GR</b>			<b>HRS.</b>	<b>B/H</b>
1956-63	2033R	190-SL Top w/plastic window	\$1,098	\$1,180	\$1,343			7	
1956-63	2033ZR	190-SL Top w/ZIPPERED plastic window	\$1,217	\$1,335	\$1,460			7	
1958-63	2034AR	300-SL Top w/plastic window	\$1,290	\$1,437	\$1,525			8	
1958-62	2035R	220-S, 220-SE Top w/plastic window (specify Black, Gray or t	\$1,262	\$1,343	\$1,423			8	
1963-72	2038R	220,250,280,300-SE Top w/plastic wndw (specify Black Gray	\$1,379	\$1,495	\$1,730			8	
1964-72	2037R	230/250/280SL Top w/plastic wndw 3 Bow. Refer to catalog	\$1,221	\$1,343	\$1,423			6	
1964-72	2039R	230/250/280SL Top w/plastic wndw 3 Bow refer to catalog	\$1,246	\$1,363	\$1,509			6	
1964-72	BS2039	Bow-straps Tan Only. 1964-72 SL						\$198	
<b>YR</b>	<b>PART NO.</b>	<b>1979-89 107 Chassis</b>	<b>ST</b>	<b>TW</b>	<b>GR</b>			<b>HRS.</b>	<b>B/H</b>
1972-89	2040R	107SL: 280/350/380/450/500/560 Top w/plastic wndw; cables	\$1,043	\$1,122	\$1,273			7	
1972-89	2041R	107SL Top, Topstitched Seams, cables & seals installed	\$1,348	\$1,437	\$1,613			7	
1972-89	WS2040	107SL L&R weather-strips for above door glass only						\$180	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1972-89	CBL2040	107SL Side	tension cables							\$169	
1972-89	BS2040	107 SL	Bow-straps	Tan Only						\$186	
<b>YR</b>	<b>PART NO.</b>	<b>1990-02</b>	<b>129 Chassis</b>		<b>ST</b>	<b>TW</b>	<b>GR</b>	<b>A5</b>		<b>HRS.</b>	<b>B/H</b>
1990-02	2042R	129SL	300/320/500/600	Top, Combo Front & Plastic Win	\$1,354	\$1,434	\$1,649	\$1,843		10	
1990-02	3142R	129SL	300/320/500/600	Top, Front Section Only	\$704	\$748	\$850	\$947		5	
1990-02	3152R	129SL	300/320/500/600	Window Section Only	\$769	\$805	\$917	\$1,014		6	
<b>YR</b>	<b>PART NO.</b>	<b>1999-03</b>	<b>CLK 208 Chassis</b>		<b>AT</b>	<b>ST</b>	<b>TW</b>	<b>A5</b>		<b>HRS.</b>	<b>B/H</b>
1999-03	2043C	CLK	320/430/CLK55	Top, no window (Chassis 208) Original window must be reused. Installation kit supplied	\$1,159	\$1,246	\$1,335	\$1,481		8	
<b>YR</b>	<b>PART NO.</b>	<b>2004-09</b>	<b>CLK 209 Chassis</b>		<b>TWR</b>	<b>A5</b>				<b>HRS.</b>	<b>B/H</b>
2004-09	2046C	CLK	320/350/500/550/CLK55/63	AMG Cabriolet (Chassis 209 \$2,096) Zippered listings, sewn in cables & retainers. Fits to existing glass	\$2,096	\$2,296				12	
<b>YR</b>	<b>PART NO.</b>	<b>MERCEDES BENZ HEADLINERS</b>			<b>BOW</b>	<b>BRO</b>				<b>HRS.</b>	<b>B/H</b>
1990-94	HL2042	129SL	300/500/600	Headliner	\$653						
1995-02	HL2042L	129SL	320/500/600	Headliner		\$843					
1999-03	HL2043	CLK	320/430/CLK55	Headliner, w/factory style retainers		\$1,532					
<b>YR</b>	<b>PART NO.</b>	<b>MERCURY</b>			<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1961-62	6503	Monterey Top,	Front Section Only		\$713	\$1,180				6	26.75
1961-62	PC6503	Plastic Window	Section Only for 6503 Top		\$312	\$511				3	
1963	6504	Monterey Top,	Front Section Only		\$713	\$1,180				6	23.5
1963	PC6504	Plastic Window	for 6504 Top		\$329	\$476				3	
1963-65	6101	Comet/Caliente	Top, Front Section Only		\$671	\$1,140				6	23.5
1963-65	PC6101	Plastic Window	Section Only for 6101 Top		\$329	\$476				3	
1964	6505	Monterey/Park	Lane Top, Front Section Only		\$713	\$1,180				6	23
1964	PC6505	Plastic Window	Section Only for 6505 Top		\$308	\$456				3	
1964	TN337	Non-Heated	Glass Window Section Only for 6505 Top		\$698	\$845				3	
1965-66	6506	Monterey Top,	Front Section Only		\$713	\$1,180				6	27
1965-66	PC6506	Plastic Window	Section Only for 6506 Top		\$308	\$456				3	
1965-66	TN338	Non-Heated	Glass Window Section Only for 6506 Top		\$737	\$884				3	
1965-66	CBL6506	Side Tension	Cables for 6506 Top						\$155		
1967-68	6507	Monterey/Park	Lane Top, Front Section Only		\$713	\$1,180				6	28
1967-68	PC6506	Plastic Window	Section Only for 6507 Top		\$308	\$456				3	
1967-68	TN339	Non-Heated	Glass Window Section Only for 6507 Top		\$737	\$884				3	
1967-68	CBL6506	Side Tension	Cables for 6507 Top						\$155		
1966-67	6301	Comet/Caliente	Top, Front Section Only		\$703	\$1,140				6	27
1966-67	PC6301	Plastic Window	Section Only for 6301 Top		\$308	\$456				3	
1966-67	TN319	Non-Heated	Glass Window Section Only for 6301 Top		\$729	\$875				3	
1968-71	6302	Comet/Cyclone/Montego	Top, Front Section Only		\$703	\$1,140				6	27
1968-71	PC6302	Plastic Window	Section Only for 6302 Top		\$308	\$456				3	
1968-71	TN320	Non-Heated	Glass Window Section only for 6302 Top		\$729	\$875				3	
1968-71	CBL6302	Side Tension	Cables for 6302 Top						\$155		
1969-72	6508	Monterey/Marquis	Top, Front Section Only		\$713	\$1,180				6	30
1969-72	PC6508	Plastic Window	Section Only for 6508 Top		\$308	\$456				3	
1969-72	TN340	Non-Heated	Glass Window Section Only for 6508 Top		\$737	\$884				3	
1969-72	CBL6508	Side Tension	Cables for 6508 Top						\$155		
<b>YR</b>	<b>PART NO.</b>	<b>COUGAR</b>			<b>KV</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1969-70	6205PC	Cougar Top,	Combo Front & Plastic Window Sections.		\$762	\$1,180				8	19.5
1969-70	6205GL	Cougar Top,	Combo Front & Folding Glass Window Secti	\$1,102	\$1,645					8	19.5
1969-70	6205	Cougar Top,	Front section Only		\$584	\$1,056				6	19.5
1969-70	PC6204	Plastic Window	Section Only for 6205 Top		\$284	\$430				3	
1969-70	GL304	Folding Glass	Window Section Only for 6205 Top		\$689	\$850				3	
1969-70	CBL6205	Mustang/Cougar	Side Tension Cables						\$155		
1971-73	6206PC	Cougar Top,	Combo Front & Plastic Window Sections.		\$733	\$1,150				8	25.25
1971-73	6206TN	Cougar Top,	Combo Front & Non-Heated Glass Window Sect	\$1,102	\$1,524					8	25.25
1971-73	6206	Cougar Top,	Front Section Only		\$584	\$1,180				6	25.25
1971-73	PC6206	Plastic Window	Section Only for 6206 Top		\$299	\$445				3	
1971-73	TN306	Non-Heated	Glass Window Section Only for 6206 Top		\$660	\$808				3	
1971-73	CBL6206	Mustang/Cougar	Side Tension Cables						\$155		
<b>YR</b>	<b>PART NO.</b>	<b>CAPRI</b>			<b>RC</b>				<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1990-93	6215**	Capri Top **See	Web or Catalog Diagram for 1993 model		\$817					6	
1993-94	6216**	Capri Top **See	Web or Catalog Diagram for 1993 model		\$817					6	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1990-93	CBL6215	Side Tension	Cables for 6215 Top							\$139		
1993-94	CBL6216	Side Tension	Cables for 6216 Top							\$139		
1990-94	CBL621Q	Quarter Flap	Cables for 6215 and 6216 Tops							\$321		
<b>YR</b>	<b>PART NO.</b>	<b>MINI COOPER</b>	<b>PERMALOK Bonded Window</b>	<b>AT</b>	<b>ST</b>	<b>TWR</b>	<b>A5B</b>	<b>HRS.</b>	<b>B/H</b>			
2004-08	2760C	Top with Htd	Glass, Rain-Guards, original style extrusions &	\$1,596	\$1,747	\$1,893	N/A	7				
2009-13	2762C	Top with Htd	Glass, Rain-Guards, original style extrusions & r	NA	\$2,139	\$2,268	\$2,526	7				
<b>YR</b>	<b>PART NO.</b>	<b>MITSUBISHI</b>	<b>PERMALOK Bonded Window</b>	<b>AT</b>	<b>SF</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1996-99	2475C	Eclipse Top	with Heated Glass	\$1,092	\$1,245			7				
2000-05	2476C	Eclipse Top	with Heated Glass	\$1,092	\$1,245			7				
2006-09	2477C	Eclipse Top	with Heated Glass	\$1,298	\$1,465			7				
		Eclipse	Headliners									
1996-99	HL2475	Eclipse	Headliner							\$503		
2000-05	HL2476	Eclipse	Headliner							\$503		
2006-09	HL2477	Eclipse	Headliner	**Customer must supply OEM headliner to re-use plastic parts**							\$541	
1996-99	CBL2475	Side Tension	Cables for 2475 Top							\$155		
2000-05	CBL2476	Side Tension	Cables for 2476 Top							\$169		
<b>YR</b>	<b>PART NO.</b>	<b>MG</b>	<b>TC, TD, TF</b>	<b>CG</b>	<b>EF</b>	<b>ST</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1946-49	21X0	MG - TC, Top	Only	\$704	\$762	\$1,262				6		
1946-49	21X0D	MG - TC, Top	with Dual Plastic Rear Windows	\$822	\$892	\$1,380				6		
1946-49	SC1X0	MG - TC Side	Curtains	\$536	\$582	\$711				3.5		
1946-49	11X0	MG - TC	Tonneau, Side Zippers	\$625	\$679	\$1,146				3		
1946-49	TIRE	MG - TC Tire	Cover	\$319	\$342	\$502						
1946-49	BSTC	Bow Straps	for TC, TD, TF. Specify Material & Color					\$251				
1950-52	2100	MG - TD, Top,	Only	\$704	\$762	\$1,262				6		
1950-52	SC100	MG - TD Side	Curtains	\$536	\$582	\$711				3.5		
1953	2101	MG - TD, Top	Only	\$704	\$762	\$1,262				6		
1953	SC101	MG - TD Side	Curtains	\$536	\$582	\$711				3.5		
1950-53	1100	MG - TD Tonneau	Cover	\$641	\$696	\$1,173				6		
1954-55	2102	MG - TF and TF	- 1500, Top Only	\$704	\$762	\$1,262				6		
1954-55	SC102	MG - TF and TF	- 1500 Side Curtains	\$536	\$582	\$711				3.5		
1954-55	1102	MG - TF Tonneau		\$641	\$696	\$1,173				3.5		
1950-55	TIRE D	MG - TD, TF	Disc Wheel Tire Cover	\$311	\$334	\$502						
1950-55	TIRE W	MG - TD, TF	Wire Wheel Tire Cover	\$311	\$334	\$502						
<b>YR</b>	<b>PART NO.</b>	<b>MGA</b>		<b>CG</b>	<b>EF</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>		
1956-60	2107	MGA Roadster	Top. Has seam across deck, 1-listing.	\$704	\$762	\$1,087	\$1,262			4		
1956-60	2109	MGA Roadster	Original Style Top. One-piece deck, no listing.	\$704	\$762	\$1,144	\$1,262			4		
1956-60	1107	MGA Roadster	Tonneau Cover	\$553	\$599	\$905	\$1,036			3		
1961-62	2177	MGA MK II	Roadster Top	\$704	\$762	\$1,085	\$1,262			4		
1961-62	1177	MGA MK II	Roadster Tonneau Cover	\$553	\$599	\$934	\$1,036			3		
<b>YR</b>	<b>PART NO.</b>	<b>MIDGET</b>		<b>CG</b>	<b>EF</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>		
1961-64	2166	Midget MK I,	Sprite MK II Top	\$704	\$762	\$1,100	\$1,262			4		
1961-64	1166	Midget MK I,	Sprite MK II Tonneau Cover	\$625	\$679	\$1,007	\$1,146			3		
1965-66	2167	Midget MK II,	Sprite MK III Top	\$704	\$762	\$1,100	\$1,262			4		
1965-66	1167	Midget MK II,	Sprite MK III Tonneau Cover	\$597	\$647	\$1,007	\$1,110			3		
1965-66	1167F	Midget MKII,	Sprite MK III Tonneau with Flap	\$684	\$745	\$1,066	\$1,241			3		
1967-69	2167A	Midget MK III,	67-70 Sprite MK IV Top	\$704	\$762	\$1,100	\$1,262			4		
1967-69	1167A	Midget MK III,	67-70 Sprite Mk IV Tonneau Cover	\$670	\$728	\$1,066	\$1,228			3		
1970-80	2168	Midget MK III,	70-71 Sprite MK IV Top	\$704	\$762	\$1,100	\$1,262			4		
1970-80	1168H	Midget MK III,	70-71 Sprite MK IV Tonneau Cover	\$684	\$745	\$1,066	\$1,241			3		
<b>YR</b>	<b>PART NO.</b>	<b>MGB and MGC</b>		<b>CG</b>	<b>EF</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>		
1962-63	2188	MGB Top		\$748	\$812	\$1,128	\$1,290			4		
1962-63	1188	MGB Tonneau	Cover	\$641	\$696	\$1,020	\$1,173			3		
1963-70	2188A	MGB, MGC Top,	for Stowaway Frame	\$748	\$812	\$1,128	\$1,290			4		
1963-70	2188AZ	MGB, MGC Top	with Zipper, for Stowaway Frame	\$924	\$1,004	\$1,305	\$1,465			4		
1963-70	2189	MGB, MGC Top,	for Folding Frame	\$748	\$812	\$1,128	\$1,290			4		
1963-70	2189Z	MGB, MGC Top	with Zipper, for Folding Frame	\$924	\$1,004	\$1,305	\$1,465			4		
1963-70	1189	MGB, MGC	Tonneau Cover	\$641	\$696	\$1,020	\$1,173			3		
1963-70	1189H	MGB, MGC	Tonneau Cover with headrest pockets	\$655	\$712	\$1,036	\$1,187			3		
1971-76	2190	MGB Top		\$762	\$826	\$1,144	\$1,290			4		
1977-80	2191	MGB Top, Zipper	Window	\$777	\$843	\$1,159	\$1,305			4		
1971-80	1190	MGB Tonneau	Cover	\$597	\$647	\$1,007	\$1,110			3		



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1971-80	1190F	MGB Tonneau	Cover, with flaps	\$625	\$679	\$1,036	\$1,146	3		
1971-80	1190H	MGB Tonneau	Cover, with headrest pockets	\$641	\$696	\$1,020	\$1,173	3		
1971-80	1190HF	MGB Tonneau	Cover, with headrest pockets and flaps	\$655	\$712	\$1,125	\$1,271	3		
<b>YR</b>	<b>PART NO.</b>	<b>MGF (ROVER)</b>		<b>ST</b>				<b>HRS.</b>	<b>B/H</b>	
1996-98	2192PC	MGF Top with	deck seams & Green Tint Plastic Window	\$1,290				8		
1996-98	2192C	MGF Top Only,	with deck seams	\$905				6		
1998	2193PC	MGF, MGTF Top	& Green PC, No rain-guards, No deck seam	\$1,290				8		
1998	2193C	MGF, MGTF Top	Only, No Rain-guards, No deck seams	\$905				6		
1998-04	2194PC	MGTF Top &	Green Tint PC; Rain-guards, No deck seams	\$1,363				8		
1998-04	2194C	MGTF Top,	Rain-guards, No deck seams	\$933				6		
1996-04	PC2192	Green Plastic	Window for above tops	\$556				3		
<b>YR</b>	<b>PART NO.</b>	<b>MORGAN</b>		<b>CG</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>	
1954-56	1289	Morgan Tonneau		\$713	\$1,195	\$1,374		3		
1959-65	1291	Morgan Tonneau		\$713	\$1,195	\$1,374		3		
1966-On	1292	Morgan Drophead	Coupe Tonneau	\$713	\$1,195	\$1,374		3		
<b>YR</b>	<b>PART NO.</b>	<b>MORRIS MINOR</b>		<b>CG</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>	
1957-69	2113	Morris Minor	Convertible 1000 Top	\$903	\$1,421	\$1,598		8		
<b>YR</b>	<b>PART NO.</b>	<b>NASH</b>		<b>KV</b>	<b>EV</b>			<b>HRS.</b>	<b>B/H</b>	
1954-58	2500	Nash Metropolitan Top w/1	Plastic Window (Will also fit 59-60	\$627	\$1,075			6		
1959-60	2501	Nash Metropolitan Top w/3	Plastic Windows (Will also fit 54-6	\$627	\$1,075			6		
<b>YR</b>	<b>PART NO.</b>	<b>NISSAN</b>		<b>ST</b>	<b>TW</b>			<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1992-94	2130CPC	Nissan 240SX	Top, Combo Front & Plastic Window Sections	\$1,070	\$1,144			6		
1992-94	HL2130	Nissan 240SX	Headliner					\$620		
1993-95	2140C	Nissan 300ZX	Top w/3 plastic windows	\$1,217	\$1,290			6		
<b>YR</b>	<b>PART NO.</b>	<b>Nissan Z series</b>	<b>PERMALOK Bonded Window</b>	<b>AT</b>	<b>HV</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>	
2004-09	2150	Nissan 350Z Top	w/ Heated glass. Factory style retainers	\$1,427	\$1,517	\$1,779		8		
2010-13	2151	Nissan 370Z Top	w/ Heated glass. Factory style retainers	\$1,725	\$1,854	\$2,073		8		
<b>YR</b>	<b>PART NO.</b>	<b>OLDSMOBILE</b>		<b>KV</b>	<b>SF</b>			<b>HRS.</b>	<b>B/H</b>	
1959-60	7505	Olds 88/98 Top,	Front Section Only	\$655	\$1,221			6	23	
1959-60	PC7505	Plastic Window	Section Only for 7505 Top	\$312	\$459			3		
1961-64	7506	Olds 88/98 Top,	Front Section Only	\$655	\$1,221			6	25	
1961-64	PC7506	Plastic Window	Section Only for 7506 Top	\$308	\$459			3		
1961-64	GL402	Non Heated	Glass Window Section Only for 7506 Top. See V	\$737	\$933			3		
1962-63	7301	F85/Cutlass	Top, Front Section Only	\$644	\$1,221			6	21.75	
1962-63	PC7301	Plastic Window	for 7301 Top	\$308	\$456			3		
1964-65	7302	F82/Cutlass	Top, Front Section Only	\$627	\$1,221			6	20.5	
1964-65	PC7302	Plastic Window	for 7302 Top	\$308	\$456			3		
1966-67	7303	F85/Cutlass/442	Top, Front Section Only	\$611	\$1,180			6	22	
1966-67	PC7303	Plastic Window	Section Only for 7303 Top	\$308	\$456			3		
1962-67	GL401	Non Heated Glass	Window Section Only for 7301,7302,7303	\$746	\$933			3		
1966-67	CBL7303	Side Tension	Cables for 7303 Top					\$155		
1965-70	7507PC	Delta 88/Starfire Top,	Combo Fnt & Plastic Wndw Section w/2	\$880	\$1,437			8		
1965-70	7507T5	Delta 88/Starfire Top,	Combo Fnt & Non Htd Glass Wndw Section	\$1,204	\$1,729			8		
1965-70	7507T7	Delta 88/Starfire Top,	Combo Fnt & Non Htd Glass Wndw Section	\$1,204	\$1,729			8		
1965-70	7507	Delta 88/Starfire Top,	Front Section Only	\$627	\$1,180			6	27.5	
1965-70	7608	Olds 98 Top,	Front Section Only	\$627	\$1,180			6		
1965-70	PC7507	Plastic Window	Section Only for 7507and 7608 tops	\$329	\$476			3		
1965-70	TN465	Non-Heated	Glass Window section Only w/Zipper for 7507 an	\$706	\$852			3		
1965-70	TN467	Non-Heated	Glass Window Section Only, No Zipper for 7507	\$694	\$841			3		
1965-72	PD6572	Original Style	Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).					\$427		
1965-70	CBL7507	Side Tension	Cables for 7507 top					\$155		
1965-70	CBL760	Side Tension	Cables for 7607/7608 Top					\$155		
1968-72	7304PC	Cutlass/F85/442	Top, Combo Front & Plastic Window Section	\$777	\$1,343			8	Fixed	
1968-72	7304APC	Cutlass/F85/442	Top, Combo Front & Plastic Window Section	\$777	\$1,343			8	20.75	
1968-72	7304TN	Cutlass/F85/442	Top, Combo Front & Non Htd Glass Window	\$1,161	\$1,770			9	Fixed	
1968-72	7304ATN	Cutlass/F85/442	Top, Combo Fnt & Non Htd Wndw Sections	\$1,230	\$1,839			9	20.75	
1968-72	7304	Cutlass/F85/442	442Top, Front Section Only	\$591	\$1,098			6	Fixed	
1968-72	7304A	Cutlass/F85/442	442Top, Front Section Only, Floating Bow	\$644	\$1,180			6	20.75	
1968-72	PC7304	Plastic Window	Section Only for 7304 Top	\$262	\$408			3		
1968-72	TN404	Non-Heated	Glass Window Section Only for 7304 Top	\$685	\$831			3		





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1968-72	WB7304	Well Liner for 7304 and 7304A Tops							\$343
1965-72	PD6572	Original Style Tapered Top Pads for GM *Fullsize & Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).							\$427
1968-72	CBL7304	Side Tension Cables for 7304 and 7304A Tops							\$155
<b>YR</b>	<b>PART NO.</b>	<b>"SCISSOR TOP"</b>	<b>KV</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1971-76	7509PC	Delta 88/98/Royale Top, Combo Fnt & Non-Orig. Plastic Winc	\$924	\$1,509		10			
1971-76	7509TN	Delta 88/98/Royale Top Combo Fnt & Non Htd Glass Window	\$1,161	\$1,729		10			
		Reuse wndw brackets							
1971-76	7509HD	Delta 88/98/Royale Top, Combo Fnt & Htd Glass Wndw.Reus	\$1,409	\$2,015		10			
1971-76	7509	Delta 88/98/Royale Top, Front Section Only	\$611	\$1,098		7			
1971-76	TN409	Non-Heated Glass Window Section Only for 7509. Reuse wnc	\$706	\$850		3			
1971-76	HD409	Heated Glass Window Section Only for 7509 Top. Reuse wnc	\$982	\$1,128		7			
1971-76	PC7509	Plastic Window Section Only for 7509 Top	\$399	\$545		3			
1971	CBL750	GM Scissor Top Side Tension Cables							\$237
1972-76	CBL7509	GM Scissor Top Side Tension Cables							\$208
1972-76	WB7509	Well Liner for 7509 Top							\$381
1984-86	7315	Ciera, Hess & Eisenhardt Top, Front Section Only	\$697	\$1,180		6	18.5		
1984-86	PC7315	Plastic Window Section Only for 7315 Top	\$360	\$511		3			
1991-95	7305	Cutlass, Cars & Concepts Top, Front Section Only (Window	\$655	\$1,098		6			
<b>YR</b>	<b>PART NO.</b>	<b>OPEL</b>	<b>KV</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>		
1986-93	2849	Opel Kadett E, Astra, Monza Top, 5 Boot Loops	\$850	\$1,583		8			
1986-93	2850	Opel Kadett E, Astra, Monza Top, 6 Boot Loops	\$850	\$1,583		8			
<b>YR</b>	<b>PART NO.</b>	<b>2001-05 Astra</b>	<b>ST</b>	<b>TW</b>		<b>HRS.</b>	<b>B/H</b>		
2001-05	2852C	Opel/Holden Astra Top with Heated Glass	\$1,908	\$2,084		8			
<b>YR</b>	<b>PART NO.</b>	<b>PEUGEOT</b>	<b>KV</b>	<b>ST</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1967-75	2704	Peugeot 204, 304 Top with Plastic Window	\$718	\$1,363		6			
1969-83	2705	Peugeot 504 Top with Plastic Window	\$866	\$1,598		8			
1984-92	2706W	Peugeot 205 Top and Plastic Window	\$968	\$1,481		6			
1984-92	2706WL	Same as 2706W top, with OE style white lining in curtain	\$1,079	\$1,583		6			
1984-92	2706	Peugeot 205 Top Only (No Window)	\$647	\$933		6			
1984-92	PC2706	Plastic Window Section Only for 2706 Top	\$550	\$697		3			
1984-92	PC2706L	Plastic Window Section Only w/white lining for 2706 Top	\$550	\$697		3			
1984-92	HL2706	Peugeot 205 Headliner							\$506
1994-04	2707C	Peugeot 306 (All) Top, No Zipper Window		\$1,301		8			
1994-00	HL2707	Peugeot 306 (All) Headliner							\$506
<b>YR</b>	<b>PART NO.</b>	<b>PLYMOUTH</b>	<b>KV/CH</b>	<b>EV</b>	<b>SF</b>	<b>HRS.</b>	<b>B/H</b>		
1963-64	5100	Valiant/Signet Top, Front Section Only	\$697	\$812	\$1,140	6	25.75		
1963-64	PC5100	Plastic Window Section Only for 5100 Top	\$323	\$346	\$469	3			
1965-66	5102	Valiant/Signet Top, Front Section Only	\$671	\$812	\$1,098	6	24.5		
1965-66	PC5102	Plastic Window Section Only for 5102 Top	\$323	\$346	\$469	3			
1965-66	5506	Fury Top, Front Section Only	\$749	\$886	\$1,301	6	27.5		
1965-66	PC5506	Plastic Window Section Only for 5506 Top	\$323	\$346	\$469	3			
1967-68	5508	Fury Top, Front Section Only	\$749	\$886	\$1,221	6	29.5		
1967-68	PC5508	Plastic Window Section Only for 5508 Top	\$323	\$346	\$511	3			
1967-68	TN151	Non-Heated Glass Window Section Only for 5508 Top	\$819	\$880	\$963	3			
1969-70	5510	Fury Top, Front Section Only	\$749	\$886	\$1,221	6	33.25		
1969-70	PC5510	Plastic Window for 5510 Top	\$404	\$438	\$550	3			
1969-70	TN153	Non-Heated Glass Window for 5510 Top	\$801	\$845	\$947	3			
1966	5507	Belvedere/ Satellite Top, Front Section Only	\$749	\$886	\$1,221	6	27		
1966	PC5507	Plastic Window Section for 5507 Top	\$323	\$346	\$469	3			
1967-70	5509	Belvedere/GTX/ Satellite/ Roadrunner Top, Front Section Onl	\$749	\$886	\$1,221	6	23.25		
1967-70	PC5509	Plastic Window Section Only for 5509 Top	\$404	\$438	\$550	3			
1967-70	TN152	Non-Heated Glass Window Section Only for 5509 Top	\$855	\$925	\$1,003	3			
1967-69	5301	Barracuda Top, Front Section Only	\$706	\$836	\$1,180	6	26.25		
1967-69	PC5301	Plastic Window Section Only for 5301 Top	\$335	\$369	\$481	3			
1967-69	TN131	Non-Heated Glass Window Section Only for 5301 Top	\$737	\$768	\$884	3			
1970-71	5302	Barracuda Top, Front Section Only	\$704	\$850	\$1,221	6	22.5		
1970-71	PC5302	Plastic Window Section Only for 5302 Top	\$335	\$369	\$478	3			
1970-71	TN132	Non-Heated Glass Window Section Only for 5302 Top	\$737	\$768	\$884	3			
<b>YR</b>	<b>PART NO.</b>	<b>PONTIAC</b>	<b>KV</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>		
1955-57	7502	Bonneville/Starchief Top, Front Section Only	\$743	\$1,180		6	20.5		





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1955-57	PC7502	Plastic Window	Section only for 7502 Top	\$329	\$476		3	
1958	7504	Bonneville/Cheftain	Top, Front Section Only	\$726	\$1,180		6	23
1958	PC7504	Plastic Window	Section only for 7504 Top	\$323	\$469		3	
1959-60	7505	Bonneville/Catalina	Top, Front Section Only	\$655	\$1,221		6	23
1959-60	PC7505	Plastic Window	Section only for 7505 Top	\$312	\$459		3	
1961-64	7506	Bonneville/Catalina	Top, Front Section Only	\$655	\$1,221		6	25
1961-64	PC7506	Plastic Window	Section only for 7506 Top	\$308	\$459		3	
1961-64	GL402	Non Heated Glass	Window Section Only for 7506 Top. See V	\$737	\$933		3	
1962-63	7301	Lemans/Tempest	Top, Front Section Only	\$644	\$1,221		6	21.75
1962-3	PC7301	Plastic Window	Section Only for 7301 Top	\$308	\$456		3	
1964-65	7302	Lemans/Tempest/GTO	Top, Front Section Only	\$627	\$1,221		6	20.5
1964-65	PC7302	Plastic Window	Section Only for 7302 Top	\$308	\$456		3	
1966-67	7303	Lemans/Tempest/GTO	Top, Front Section Only	\$611	\$1,180		6	22
1966-67	PC7303	Plastic Window	Section Only for 7303 Top	\$308	\$456		3	
1962-67	GL401	Non Heated Glass	Window Section Only for 7301,7302,7303	\$746	\$933		3	
1965-72	PD6572	Original Style	Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).			\$427		
1966-67	CBL7303	Side Tension	Cables for 7303 Top			\$206		
1965-70	7507PC	Bonneville/Catalina/Gran	Prix/Parisienne Top, Combo Fnt & F w/Zipper	\$880	\$1,437		8	
1965-70	7507T5	Bonneville/Catalina/Gran	Prix/Parisienne Top, Combo Fnt & F w/Zipper	\$1,204	\$1,729		8	
1965-70	7507T7	Bonneville/Catalina/Gran	Prix/Parisienne Top, Combo Fnt & F No Zipper	\$1,204	\$1,729		8	
1965-70	7507	Bonneville/Catalina/Grand	Prix/Parisienne Top, Front Section	\$627	\$1,180		6	27.5
1965-70	PC7507	Plastic Window	Section Only for 7507 Top	\$329	\$476		3	
1965-70	TN465	Non-Heated Glass	Window Section Only w/Zipper for 7507	\$706	\$852		3	
1965-70	TN467	Non-Heated Glass	Window Section Only, No Zipper for 7507	\$694	\$841		3	
1965-72	PD6572	Original Style	Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).			\$427		
1965-70	CBL7507	Side Tension	Cables for 7507 Top			\$155		
1968-72	7304PC	Lemans/Tempest	Top, Combo Front & Plastic Window Sectio	\$777	\$1,343		8	Fixed
1968-72	7304APC	Lemans/Tempest	Top, Combo Front & Plastic Wndw Section	\$794	\$1,360		8	20.75
1968-72	7304TN	Lemans/Tempest	Top, Combo Front & Non Htd Glass Windo	\$1,161	\$1,770		8	Fixed
1968-72	7304ATN	Lemans/Tempest	Top, Combo ont & Non Htd Wndw Sections	\$1,230	\$1,839		8	20.75
1968-72	7304	Lemans/Tempest	Top, Front Section Only	\$591	\$1,098		6	Fixed
1968-72	7304A	Lemans/Tempest	Top, Front Section Only. Floating Bow	\$644	\$1,180		6	20.75
1968-72	PC7304	Plastic Window	Section Only for 7304 Top	\$262	\$408		3	
1968-72	TN404	Non-Heated Glass	Window Section Only for 7304 Top	\$685	\$831		3	
1968-72	WB7304	Well Liner for 7304 and 7304A	Tops			\$343		
1965-72	PD6572	Original Style	Tapered Top Pads for GM *Fullsize and Midsize (*Except Scissor tops, Corvette, Camaro, Corvair).			\$427		
1968-72	CBL7304	Side Tension	Cables for 7304 and 7304A Tops			\$155		
<b>YR</b>	<b>PART NO.</b>	<b>"SCISSOR TOP"</b>		<b>KV</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1971-76	7509PC	Catalina/Grandville/Brougham	Top, Combo Fnt & Non-Orig. F	\$924	\$1,509		10	
1971-76	7509TN	Catalina/Grandville/Brougham	Top, Combo Fnt & Non Htd Gl	\$1,161	\$1,729		10	
1971-76	7509HD	Catalina/Grandville/Brougham	Top, Combo Fnt & Htd Glass W	\$1,409	\$2,015		10	
1971-76	7509	Catalina/Grandville/Brougham	Top, Front Section Only	\$611	\$1,098		7	
1971-76	TN409	Non-Htd Glass	Wndw Section Only for 7509. Reuse wndw br	\$706	\$850		3	
1971-76	HD409	Heated Glass	Window Section Only for 7509 Top. Reuse wnc	\$982	\$1,128		3	
1971-76	PC7509	Plastic Window	Section Only for 7509 Top	\$399	\$545		10	
1971	CBL750	1971 GM Scissor	Top Side Tension Cables			\$237		
1972-76	CBL7509	1972-76 GM	Scissor Top Side Tension Cables			\$208		
1971-76	WB7509	Well Liner for 7509	Top			\$381		
<b>YR</b>	<b>PART NO.</b>	<b>FIREBIRD</b>		<b>KV</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1967-70	7201PC	Camaro/Firebird	Top, Combo Front & Plastic Window Section	\$733	\$1,301		8	22.5
1967-70	7201ZPC	Camaro/Firebird	Top, Combo Front & Plastic Window Section	\$794	\$1,362		8	22.5
1967-70	7202GL	Camaro/Firebird	Top, Combo Fnt & Folding Non Htd Wndw	\$1,131	\$1,689		8	22.5
		Deep Well Liner (WB7202) is required						



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1967-70	7201	Camaro/Firebird	Top, Front Section Only for 7201 top only	\$591	\$1,098		6	22.5	
1967-70	7202	Camaro/Firebird	Top, Front Section Only for 7202 top only	\$591	\$1,098		6	22.5	
1967-70	PC7201	Plastic Window	Section Only for 7201 Top. No Zipper	\$266	\$412		3		
1967-70	PC7201Z	Plastic Window	Section Only for 7201Top. w/Zipper	\$284	\$430		3		
1967-70	GL304	Non Heated	Folding Glass Window Section Only for 7202 Top	\$689	\$850		3		
			Deep well liner (WB7202) is required.						
1967-70	WB7202	Deep Well Liner	required for 67-70 Camaro/Firebird w/folding glass			\$350			
1967-70	CBL721	Camaro/Firebird	Side Tension Cables for 7201/7202 Tops			\$184			
1987-88**	7203	Camaro/Firebird	Top w/ Plastic Window **See Web or Catalo	\$697	\$1,061		6		
1988-91**	7204	Camaro/Firebird	Top w/ Plastic Window **See Web or Catalo	\$697	\$1,061		6		
1990-92**	7205	Camaro/Firebird	Top w/ Plastic Window **See Web or Catalo	\$697	\$1,061		6		
1990-93**	7206	Camaro/Firebird	Top w/ Plastic Window **See Web or Catalo	\$704	\$1,085		6		
			**Measurement system is approximate, and based on OEM top. This item is not guaranteed to fit						
			Carefully compare our top to the old one BEFORE installing. This item is not returnable if installation has started.						
1993	972L	Camaro/Firebird	Headliner			\$649			
1987-93	CBL723	Camaro/Firebird	Side Tension Cables for 7203/7204/7205/7206 Tops			\$155			
<b>YR</b>	<b>PART NO.</b>	<b>FIREBIRD</b>		<b>KV</b>	<b>AT</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1994-02	7210HD	Camaro/Firebird	Top, Combo Front & Heated Glass Window	\$1,131	\$1,230	\$1,454		8	23.25
1994-02	7210	Camaro/Firebird	Top, Front Section Only. No seam at rear bo	\$655	\$709	\$946		6	23.25
			*Rear bow tack-strip (not included) is required for 1994 models. Available N/C upon request .						
1994-02	HD720	Camaro/Firebird	Heated Glass Window Section Only for 7	\$660	\$715	\$808		3	
1994-02	973L	Camaro/Firebird	Headliner				\$559		
1994-02	CBL7210	23" OAL	Side Tension Cables for Camaro Top				\$155		
1994-02	CBL7210A	29" OAL	Side Tension Cables for Camaro Top				\$155		
<b>YR</b>	<b>PART NO.</b>	<b>PONTIAC SUNBIRD &amp; SUNFIRE</b>		<b>KV</b>	<b>SF</b>		<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1983-87	7310PC	Cavalier/Sunbird	Top, Combo Front Section & Plastic Wir	\$748	\$1,301			8	21.5
1983-87	7310	Cavalier/Sunbird	Top, Front Section Only	\$532	\$1,016			6	21.5
1983-87	PC7310	Plastic Window	Section Only for 7310 Top. Exposed color trin	\$335	\$481			3	
1983-87	CBL7310	Cavalier/Sunbird	Side Tension Cables				\$155		
1983-87	CBL7310R	Cavalier/Sunbird	Side Rear Flap Cables				\$155		
1988-92	7311PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw. **See Cat	\$704	\$1,262			8	26.25
1988-92*	7311	Cavalier/Sunbird	Top,Fnt Section Only. Uses wire-on at rear.	\$532	\$1,056			6	26.25
1988-92*	PC7311	Plastic Window	Section Only for 7311 Top. No exposed color	\$284	\$430			3	
1988-92	CBL7311	Cavalier/Sunbird	Side Tension Cables				\$155		
1988-92	CBL7310R	Cavalier/Sunbird	Side Rear Flap Cables				\$155		
1992-93*	7312PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw Sections. *	\$806	\$1,407			8	27
1992-93*	7312TN	Cavalier/Sunbird	Top, Combo Fnt & Non Htd Glass Wndw. *S	\$969	\$1,115			8	27
1992-93*	7312HD	Cavalier/Sunbird	Top, Combo Fnt & Htd Glass Wndw. *See C	\$1,058	\$1,496			8	27
1992-93*	7312	Cavalier/Sunbird	Fnt Sec Only. Header not bound, No wire-or	\$532	\$1,016			6	27
1992-93*	TN412	Non-Heated	Glass Window Section Only for 7312 and 7313 T	\$558	\$706			3	
1992-93*	HD412	Heated Glass	Window Section for 7312 and 7313 Top	\$660	\$828			3	
1992-93*	PC7312	Plastic Window	Section Only for 7312, 7313 Top. Exposed Cr	\$360	\$506			3	
1992-93	CBL7312	Cavalier/Sunbird	Side Tension Cables				\$155		
1992-93	CBL7310R	Cavalier/Sunbird	Rear Flap Cables				\$155		
1993½-94*	7313PC	Cavalier/Sunbird	Top, Combo Fnt & Plastic Wndw Sec. *See	\$704	\$1,262			8	27
1993½-94*	7313TN	Cavalier/Sunbird	Top, Combo Fnt & Non-Htd Glass . *See Ca	\$941	\$1,524			8	27
1993½-94*	7313HD	Cavalier/Sunbird	Top, Combo Fnt & Htd Glass Sections. *See	\$1,058	\$1,597			8	27
1993½-94*	7313	Cavalier/Sunbird	Top, Fnt Section Only.	\$532	\$1,056			6	27
			Binding/pocket at header. *See Catalog/Web						
1993½-94*	TN412	Non-Heated	Glass Window Section Only for 7312 and 7313 T	\$558	\$706			3	
1993½-94*	HD412	Heated Glass	Window Section Only for 7312 and 7313 Top	\$660	\$828			3	
1993½-94*	PC7312	Plastic Window	Section Only for 7312, 7313 Top. Exposed Cr	\$360	\$506			3	
1993½-94*	CBL7312	Cavalier/Sunbird	Side Tension Cables				\$155		
1993½-94*	CBL7310R	Cavalier/Sunbird	Rear Flap Cables				\$155		
1995-98	7316PC	Cavalier/Sunfire	Top, Combo Fnt & Plastic Wndw Sections,	\$777	\$1,301			8	27.5
1995-98	7316TN	Cavalier/Sunfire	Top, Combo Fnt & Non Htd Glass Window w	\$941	\$1,526			8	27.5
1995-98	7316HD	Cavalier/Sunfire	Top, Combo Fnt & Htd Glass Wndw w/Dec	\$1,013	\$1,600			8	27.5
1995-98	7316	Cavalier/Sunfire	Top, Front Section Only, w/Deck Seams.	\$532	\$1,056			6	27.5
1998½-00	7317PC	Cavalier/Sunfire	Top, Combo Fnt & Plastic Wndw Sections. N	\$777	\$1,301			8	27.5
1998½-00	7317TN	Cavalier/Sunfire	Top, Combo Fnt & Non Htd Wndw Sections.	\$941	\$1,526			8	27.5
1998½-00	7317HD	Cavalier/Sunfire	Top, Combo Front & Htd Wndw Sections. Nc	\$969	\$1,600			8	27.5



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



YR	PART NO.	DESCRIPTION	SS	AT	SF	MISC.	HRS.	B/H	
1998½-00	7317	Cavalier/Sunfire Top, Front Section Only, No deck seams.	\$541	\$1,056			6	27.5	
<b>1998-00 Cavalier/Sunfire</b>									
1995-00	TN416	Non-Heated Glass Window Section Only for 7316, 7317 Top	\$558	\$602	\$706		3		
1995-00	HD416	Heated Glass Window Section Only for 7316, 7317 Top	\$660	\$715	\$828		3		
1995-00	PC7316	Plastic Window Section Only for 7316, 7317 Top	\$360	\$388	\$506		3		
1995-00	HL7316	Cavalier/Sunfire Headliner				\$396			
1995-00	CBL7316	Cavalier/Sunfire Side Tension Cables				\$184			
<b>PORSCHE</b>									
YR	PART NO.	DESCRIPTION	ST	TW	GR		HRS.	B/H	
1955-56	2000R	Porsche 356A Speedster Top, Low Bow	\$1,193	\$1,332	\$1,558		5	13	
1955-56	2001R	Porsche 356A Speedster Top, High Bow	\$1,193	\$1,332	\$1,558		5	15	
1957-58	2002R	Porsche 356A Speedster Top, High Bow	\$1,153	\$1,290	\$1,518		5		
1958-59	2003R	Porsche 356A Convertible D Top	\$1,153	\$1,290	\$1,408		5	16	
1960-62	2004R	Porsche 356B Roadster Top, Low Bow	\$1,153	\$1,290	\$1,408		5		
1960-62	2006R	Porsche 356B Roadster Top	\$1,153	\$1,290	\$1,408		5	17	
1958-62	2005R	Porsche 356B Cabriolet T2-T5 Top	\$1,127	\$1,250	\$1,482		5		
1962-65	2007R	Porsche Late 356B, 356C Cabriolet Top (Specify Blk, Gray or	\$1,225	\$1,364	\$1,562		5		
1958-65	B1007R	Porsche Late 356B, 356C Cabriolet Boot	\$1,224	\$1,341	\$1,532		3		
<b>PORSCHE TARGA</b>									
YR	PART NO.	DESCRIPTION	LV	ST	TW		HRS.	B/H	
1967-94	2008	Porsche Targa, Top Cover Only	\$410	\$540	\$616		5		
1967-94	2008R	Porsche Targa, Top Cover Only, with Hand-Rolled Binding	\$450	\$580	\$654		5		
<b>PORSCHE 911 1983-1994</b>									
YR	PART NO.	DESCRIPTION	ST	TW	GR	MISC.	HRS.	B/H	
1983-85	2009R	Porsche 911SC, Carrera Top Combo Front & Plastic Window	\$1,172	\$1,264	\$1,428		10		
1983-85	2999R	Porsche 911SC, Carrera Top, Front Section Only	\$771	\$893	\$1,060		5		
1983-85	3119R	Porsche 911SC, Carrera Top, Window Section Only	\$968	\$1,070	\$1,114		5		
1986-94	2010R	911SC/Carrera 930Top, Combo Front & Plastic Window Sec	\$1,093	\$1,169	\$1,343		10		
1986-94	3100R	Porsche 911SC, Carrera Top, Front Section Only	\$810	\$893	\$1,056		5		
1986-94	3120R	Porsche 911SC, Carrera 930 Top, Window Section Only	\$974	\$1,098	\$1,114		5		
1983-94	HL999	Porsche 911, Carrera Headliner				\$261			
1983-88	P911ZSL	Porsche Original Zipper Slide				\$113			
1983	1009C	Porsche 911SC Cabriolet Tonneau Cover	\$1,387	\$1,549	\$1,871		4.5		
1983-84	1009HC	Porsche 911SC, Carrera Tonneau Cover with headrest pocket	\$1,491	\$1,696	\$2,046		4.5		
1984-85	1010C	Porsche Carrera Tonneau Cover	\$1,593	\$1,740	\$1,974		3		
1984-85	1010HC	Porsche 911, Carrera Tonneau Cover with headrest pockets	\$1,710	\$1,886	\$2,151		3		
1986-94	1011C	Porsche 911, Carrera Tonneau Cover	\$1,710	\$1,886	\$2,151		3		
1983-85	B1009R	Porsche 911, Carrera Top Boot	\$1,532	\$1,679	\$1,869		3		
1986-94	B1010C	Porsche 911, Carrera Top Boot	\$1,590	\$1,781	\$1,957		3		
<b>PORSCHE 993</b>									
YR	PART NO.	DESCRIPTION	ST	TW	GR	A5	HRS.	B/H	
1995-98	3175C	Porsche 993 top with Green Plastic Window. Zipper fits to fac	\$1,424	\$1,448	\$1,587	\$1,697	10		
<b>PORSCHE 996 PERMALOK Bonded Window</b>									
YR	PART NO.	DESCRIPTION	ST	TW	GR	A5S	MISC.	HRS.	B/H
*1999-01	3177	Porsche 996 top with Green Plastic Window. Zipper fits to fac	\$1,379	\$1,481	\$1,672	\$1,787		9	
*Fits 1999 models starting from serial # XS654806 (last 8 characters of VIN).									
*1999-01	3178	Porsche 996 Top with Heated Glass Upgrade. Zipper fits to fa	\$1,835	\$1,981	\$2,157	\$2,230		9	
*Fits 1999 models starting from serial # XS654806 (last 8 characters of VIN).									
2002-10	3179	996/997 Carrera4/S4/s/Turbo/Turbo S Cabriolet. Fits to factory glass				\$2,463			
1995-98	HL3175	993 Headliner w/original zipper					\$843		
1999-01	HL3177	996 Headliner w/original zipper. Reuse palstic retainers					\$843		
<b>PORSCHE 944, 968</b>									
YR	PART NO.	DESCRIPTION	ST	TW	GR		HRS.	B/H	
1989-94	3130C	Porsche 944, 968 Top, Combo Front & Plastic Window Sectic	\$1,388	\$1,510	\$1,609		10		
1989-94	3140C	Porsche 944, 968 Top, Front Section Only	\$835	\$924	\$996		5		
1989-94	3150	Porsche 944, 968 Top, Window Section Only	\$908	\$1,012	\$1,231		5		
<b>PORSCHE BOXSTER PERMALOK Bonded Window</b>									
YR	PART NO.	DESCRIPTION	ST	TW	A5	A5S	MISC.	HRS.	B/H
1997-02	3161	Boxster Top, with Plastic Window	\$1,005	\$1,056	\$1,211	\$1,358		8	
1997-02	3162	Boxster Top with Heated Glass Upgrade w/wiring harness	\$1,388	\$1,425	\$1,535	\$1,712		8	
2003-04	3163	Boxster Top with Heated Glass	\$1,388	\$1,425	\$1,535	\$1,712		8	
2005-10	3164	Boxster Top with Heated Glass	\$1,388	\$1,425	\$1,535	\$1,712		9	
<b>Boxster Headliners</b>									
2000-02	HL3162	986 Boxster/S Headliner reuse plastic retainer					\$799		
2003-04	HL3163	986 Boxster/S Headliner reuse plastic retainer					\$931		
2005-10	HL3164	987 Boxster Headliner					NA		
<b>RENAULT / AMC</b>									
YR	PART NO.	DESCRIPTION	KV	ST	TW		HRS.	B/H	



Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1959-62	2300	Renault	Caravelle Top with plastic window	\$762	\$1,437	\$1,598		6	
1962-64	2301	Renault	Caravelle Top with plastic window	\$762	\$1,437	\$1,598		6	
1964-68	2302	Renault	Caravelle Top with plastic window	\$894	\$1,554	\$1,715		6	22.75
1985-87	4301	AMC Alliance	Top, Front Section Only, Original Quarters	\$748	\$1,287	\$1,434		6	22.75
1985-87	4302	AMC Alliance	Top, Front Section Only, One-Piece Quarters	\$704	\$1,246	\$1,392		6	22.75
1985-87	PC4301	Plastic Window	with zipper for 4301, 4302	\$399	\$571	\$984		3	
<b>YR</b>	<b>PART NO.</b>	<b>ROLLS ROYCE</b>		<b>CG</b>	<b>BS</b>	<b>TW</b>	<b>GR</b>	<b>HRS.</b>	<b>B/H</b>
1967-92	2450R*	Silver Shadow	and Corniche Top with Plastic Window.	\$1,700	\$2,491	\$2,609	\$2,858	16	23.5
*MUST SPECIFY GRAY OR TAN WINDOW LINING									
<b>YR</b>	<b>PART NO.</b>	<b>ROVER</b>		<b>SS</b>	<b>ST</b>	<b>TW</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1992-98	2249PC	Rover 214, 216	Top, Combo Front & Plastic Window Sections	\$1,144	\$2,169	\$2,417		10	
1992-98	2250	Rover 214, 216	Top, Front Section Only	\$631	\$1,246	\$1,437		8	
1992-98	PC2250	Plastic Window	Only for 2250	\$608	\$945	\$1,136		3	
1992-98	HL2249	Rover 214, 216	Headliner				\$550		
<b>YR</b>	<b>PART NO.</b>	<b>SAAB</b>		<b>AT</b>	<b>SF</b>	<b>TW</b>	<b>GR</b>	<b>MISC.</b>	<b>HRS.</b>
<b>YR</b>	<b>PART NO.</b>	<b>SAAB 900</b>		<b>Material</b>	<b>Colour</b>	<b>Price</b>		<b>HRS.</b>	<b>B/H</b>
1986-94	2725HD	Saab 900/S Top,	Combo Front & Heated Glass Window Secti	\$1,557	\$1,747	\$1,951	\$2,304	10	
1986-94	2725C	Saab 900/S Top,	Front Section Only	\$972	\$1,098	\$1,231	\$1,465	8	23
1986-94	HD272	Saab 900/S Top,	Heated Glass Window Section Only	\$692	\$823	\$897	\$1,013	3	
1986-94	HL2725	Saab 900, 900S	Headliner				\$577		
1986-94	CBL2725	SAAB 900/S Side	Tension Cables				\$155		
<b>YR</b>	<b>PART NO.</b>	<b>1996-2003 Saab 900S/SE, 9-3</b>		<b>AT</b>	<b>SF</b>	<b>TW</b>	<b>A5</b>	<b>MISC.</b>	<b>HRS.</b>
1996-98	2728R	Saab 900S/SE	Top Only, No Window. (Reuse OE Glass)	\$1,088	\$1,221	\$1,301	\$1,628	10	
1998-03	2732C	Saab 9-3, Top	Only, No Window. (Reuse OE Glass)	\$1,088	\$1,221	\$1,301	\$1,465	10	
2004-09	2735	Saab 9-3, Top	Only, No Window. (Reuse OE Glass)	NA	NA	\$2,164	\$2,456	10	
<b>SAAB Headliners</b>									
1996-98	HL2728	Saab 900S/SE	Headliner				\$1,086		
1998-03	HL2732	Saab 9-3	Headliner				\$1,087		
1996-98	CBL2728	SAAB 900/S Side	Tension Cables				\$155		
1998-03	CBL2732	Saab 9-3					\$155		
1996-98	GL2728	Replacement	Heated Glass Only for 2728R Top				\$557		
<b>YR</b>	<b>PART NO.</b>	<b>SINGER</b>		<b>CG</b>	<b>BS</b>	<b>ST</b>		<b>HRS.</b>	<b>B/H</b>
1959-62	2605	Singer Gazelle	Top	\$832	\$1,348	\$1,465		6	
1959-62	2605P	Singer Gazelle	Top with sewn-in pads	\$1,035	\$1,494	\$1,548		6	
<b>YR</b>	<b>PART NO.</b>	<b>SUNBEAM</b>		<b>CG/KV</b>	<b>EF</b>	<b>BS</b>	<b>ST</b>	<b>HRS.</b>	<b>B/H</b>
1959-61	2611	Sunbeam Alpine	Series Top	\$932	\$1,013	\$1,358	\$1,380	6	
1961-62	2613	Sunbeam Alpine	Series II Top	\$932	\$1,013	\$1,358	\$1,380	6	
1963-65	2614	Sunbeam Alpine	Series III & IV Top	\$808	\$876	\$1,218	\$1,321	6	
1963-65	2614F	Sunbeam Alpine	Series III & IV Top w/lower flaps	\$808	\$876	\$1,218	\$1,321	6	
1963-65	1613	Alpine Series	III & IV Tonneau Cover	\$673	\$729	\$1,075	\$1,246	3	
1966-68	2614A	Alpine Series	V, Tiger, 1725 Top	\$720	\$781	\$1,164	\$1,380	5	
1966-68	1614A	Alpine Series	V, Tiger, 1725 Tonneau Cover	\$655	\$712	\$1,072	\$1,305	3	
1958-62	2615	Sunbeam Rapier	Top	\$775	\$841	\$1,250	\$1,582	7	
1958-62	2615P	Sunbeam Rapier	Top with sewn-in pads	\$963	\$1,047	\$1,402	\$1,582	7	
<b>SUZUKI</b>									
<b>YR</b>	<b>PART NO.</b>	<b>SWIFT, FIREFLY</b>		<b>KV</b>	<b>EV</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1990-93	7330	Suzuki	Swift/Firefly Top. See Catalog/Web	\$753	\$941	\$1,180		6	
1990-93	CBL7330	Side Tension	Cables for 7330 Top				\$184		
<b>YR</b>	<b>PART NO.</b>	<b>SAMURAI/SANTANA SJ413, VITARA, SIDEKICK</b>		<b>CM</b>	<b>JP</b>	<b>SF</b>		<b>HRS.</b>	<b>B/H</b>
1983-94	7349	Samurai,	Santana, SJ413, Sierra Top	\$920	\$895	\$1,790		0.5	
1989-94	7350	Sidekick,	Vitara, Complete Top	\$1,007	\$932	\$1,790		0.5	
1989-94	PC7350L	Replacement Rear	Plastic Window for OE Tops in Europe - Zipper Opens Left to Right.	\$338	\$330				
1989-94	PC7350R	Replacement Rear	Plastic Window for 7350 and USA OEM Tops - Zipper Opens Right to Left.	\$338	\$330				
1995-98	7351	Sidekick,	Vitara, Complete Top	\$1,115	\$1,062	\$2,062		0.5	
1995-98	PC7351L	Replacement Rear	Plastic Window for 7351 Top, Zipper Opens Left to Right.	\$338	\$330				
1995-98	PC7351R	Replacement Rear	Plastic Window for OE Tops in Europe, Zipper Opens Right to Left.	\$338	\$330				
1995-98	SC7351	Replacement Side	Curtains for Sidekick/Vitara	\$475	\$448	NA		NA	





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



TOYOTA								
YR	PART NO.	CELICA	AT	ST	MISC.	HRS.	B/H	
1984-85	3000PC	Celica Top, Combo Front & Plastic Window Section Only	\$1,217	\$1,290		7	20.5	
1984-85	3000	Celica Top, Front Section Only for 3000PC Top	\$778	\$852		5		
1984-85	PC3000	Plastic Window Section Only for 3000 Top	\$430	\$555		3		
1987-89	3001PC	Celica Top, Combo Front & Plastic Window Section	\$972	\$1,169		7		
1987-89	3001	Celica Top, Front Section Only for 3001PC Top	\$778	\$852		5	21.25	
1987-89	PC3001	Plastic Window Section Only for 3001 Top	\$352	\$478		3		
1987-89	HL3001	Celica Headliner			\$624			
1991-93	3002PC	Celica Wide Deck Top, Combo Fnt & Plastic Wndw Sec. See	\$959	\$1,123		7		
1991-93	3002APC	Celica Narrow Deck Top, Combo Fnt & Plastic Wndw Sec. Se	\$959	\$1,123		7		
1991-93	3002	Celica Top, Front Section Only, Wide Deck. See Catalog/W	\$778	\$852		5	22.5	
1991-93	3002A	Celica Top, Front Section Only, Narrow Deck. See Catalog/	\$778	\$852		5	22.5	
1991-93	PC3002	Plastic Window Section Only for 3002 and 3002A Tops	\$507	\$636		3		
1991-93	HL3002	Celica Headliner			\$624			
1995-99	3003HD	Celica Top, Combo Front & Heated Glass Window Sections	\$1,151	\$1,343		7		
1995-99	3003	Celica Top, Front Section Only for 3003 Top	\$635	\$810		5	24.5	
1995-99	HD303	Heated Glass Window Section for 3003 Top	\$668	\$777		3		
1995-99	HL3003	Celica Headliner	\$372	\$506				
YR	PART NO.	SOLARA	AT	ST	SFA	MISC.	HRS.	B/H
1999-03	3010HD	Solara Top, Combo Front & Heated Glass Window Sectio	\$1,202	\$1,365	NA		8	
1999-03	3010C	Solara Front Section Only for 3010 Top	\$668	\$755	NA		6	
1999-03	HD301	Heated Glass Window Section Only for 3010 Top	\$597	\$693	NA		3	
2004-09	3011C	Solara Top with PERMALOK Heated Glass BINDING MATC	NA	NA	\$1,565		8	
2004-09	3011AC	Solara Top with PERMALOK Heated Glass TAN TOP w/BL	NA	NA	\$1,565		8	
2004-09	TS3011	Solara Tension Straps				\$273		
1999-03	HL3010	Solara Headliner				\$506		
2004-09	HL3011	Solara Headliner				\$741		
YR	PART NO.	MR2	RC	AT	ST		HRS.	B/H
2000-04	3005	Toyota MR2 Top w/Heated Glass. Sewn in side cables & reta	\$1,582	\$1,622	\$1,734		8	
YR	PART NO.	TRIUMPH	CG	EF	BS	ST	HRS.	B/H
1953-55	2201	Triumph TR-2 Top	\$762	\$826	\$1,187	\$1,290	6	
1954-55	1201	1954-55 Triumph TR-2 Tonneau Cover	\$714	\$778	\$1,138	\$1,241	3	
1955-57	2202	Triumph TR-3 Top	\$762	\$826	\$1,187	\$1,290	6	
1957-61	2204	Triumph TR-3, TR-3A Top	\$762	\$826	\$1,187	\$1,290	6	
1956-63	1204	1956-63 Triumph TR-3 Tonneau Cover	\$581	\$632	\$982	\$1,064	3	
1961-65	2205	Triumph TR-4 Top	\$748	\$812	\$1,172	\$1,275	6	
1961-66	1205	1961-66 Triumph TR-4 Tonneau Cover	\$567	\$616	\$967	\$1,049	3	
1966-67	2206	Triumph TR-4A Top	\$733	\$795	\$1,159	\$1,261	6	
1966-97	1206	1966-67 Triumph TR-4A Tonneau Cover	\$567	\$616	\$967	\$1,049	3	
1967-68	2207	Triumph TR-250, TR-5 (Europe) Top	\$733	\$795	\$1,159	\$1,261	6	
1967-68	2219	Triumph TR-250, TR-5 (Europe) Top with Reflective Strip	\$952	\$1,036	\$1,217	\$1,335	5	
1967-68	2219Z	Triumph TR-250, TR-5 (EU) Top with Reflective Strip, Zipper	\$1,070	\$1,166	\$1,319	\$1,429	5	
1967-68	1207	Triumph TR-250, TR-5 (Europe) Tonneau Cover	\$567	\$616	\$967	\$1,049	3	
1969-76	2207A	Triumph TR-6 Top	\$762	\$826	\$1,187	\$1,290	4	
1969-76	2220	Triumph TR-6 Top with Reflective Stripe	\$1,041	\$1,133	\$1,290	\$1,583	4	
1969-76	1207A	Triumph TR-6 Tonneau Cover	\$567	\$616	\$967	\$1,049	3	
1969-76	1207AH	Triumph TR-6 Tonneau Cover with headrest pockets	\$641	\$696	\$1,106	\$1,228	3	
1979-81	2208	Triumph TR-7/TR-8 Top	\$894	\$972	\$1,221	\$1,343	4	
1979-81	1208	Triumph TR-7, TR-8 Tonneau Cover	\$714	\$778	\$1,138	\$1,241	3	
1963-66	2209	Triumph Spitfire 4, Mark II Top	\$704	\$762	\$996	\$1,144	5	
1963-66	1209	Triumph Spitfire 4, Mark II Tonneau Cover	\$641	\$696	\$1,106	\$1,228	3	
1967-69	2209A	Triumph Spitfire Mark III Top	\$733	\$795	\$1,159	\$1,261	5	
1967-69	1209A	Triumph Spitfire Mark III Tonneau Cover	\$641	\$696	\$1,094	\$1,271	3	
1970-71	2211	Triumph Spitfire Mark III Top	\$777	\$843	\$1,070	\$1,290	6	
1970-71	1209AH	Spitfire Mark III Tonneau Cover, with headrest pockets	\$670	\$728	\$1,080	\$1,271	3	
1970-71	1211H	Spitfire Mark III Tonneau Cover, with headrest pockets	\$641	\$696	\$1,106	\$1,228	3	
1960-70	2210	Herald, Sports Six, 1200, Vitesse, Top	\$748	\$812	\$1,172	\$1,275	6	
1971-80	2212	Triumph Spitfire Mark IV Top	\$733	\$795	\$1,159	\$1,261	4	
1971-80	1212H	Spitfire Mark IV Tonneau Cover with headrest pockets	\$641	\$696	\$1,106	\$1,228	3	
1978-80	1212AH	1978-80 Spitfire Mark IV Tonneau Cover with headrest pocke	\$641	\$696	\$1,106	\$1,228	3	





Robbins Auto Tops Canadian Suggested Retail Price List  
 Featuring Robbins complete selection of XT Budget Tops  
 August 15, 2016



1971-72	2213	Triumph Stag	Top, 3 Plastic Windows	\$996	\$1,084	\$1,379	\$1,567	8		
1972-77	2214	Triumph Stag	Top, 1 Zipper Window	\$996	\$1,084	\$1,379	\$1,567	8		
<b>VOLKSWAGEN</b>										
<b>YR</b>	<b>PART NO.</b>	<b>1954-79 BEETLE</b>		<b>KV</b>	<b>RC</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>	
1954-57	2022	Volkswagen	Beetle Top, Model 1200	\$689	\$746	\$1,085		8		
1958-62	2026	Volkswagen	Beetle Top, Model 1200	\$647	\$700	\$1,098		8		
1963-67	2027	Volkswagen	Beetle Top, Model 1200	\$647	\$700	\$1,098		8	22.5	
1963-67	B1027	1963-67 Volkswagen	Beetle Top Boot	\$586	\$638	\$1,038		1		
1968-72	2028	Volkswagen	Beetle Top, Model 1302	\$647	\$700	\$1,098		8	23.5	
1968-72	B1028	1968-72 Volkswagen	Beetle Top Boot	\$586	\$638	\$1,038		1		
1973-79	2060	Volkswagen	Beetle Top, Model 1303	\$647	\$700	\$1,098		8	23.5	
1973-79	HL2060	1973-79 VW	Beetle Headliner				\$536			
1973-79	B1060	1973-79 Volkswagen	Beetle Top Boot	\$586	\$638	\$1,047		1		
1968-79	CBL2028R	1968-79 Rear	Mounting Cable for 2028 and 2060 (each)				\$170			
1954-79	CBLVWRS	Beetle, K. Ghia, Rabbit, Cabriolet	Side Cables				\$151			
<b>YR</b>	<b>PART NO.</b>	<b>1973-78 THING</b>		<b>RS/CG</b>	<b>KV</b>	<b>RC</b>	<b>SF</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1973-78	2065	Volkswagen	Thing Top, Type 181	\$996	\$996	\$1,085	\$1,583		5	
<b>YR</b>	<b>PART NO.</b>	<b>RABBIT/GOLF I 1980-1993</b>		<b>KV</b>	<b>RC</b>	<b>SF</b>	<b>SG</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1980-93	2062	Rabbit, Cabriolet, Golf I	Top w/Rainguard Deck Seams	\$647	\$748	\$1,144	\$1,290		6	
1980-93	2063	Rabbit, Cabriolet, Golf I	Top w/o Rainguard Deck Seams	NA	\$532	NA	NA		6	
1980-81	HL961	1980-81 VW	Rabbit, Golf I Headliner					\$550		
1982-85	HL962	1982-85 Cabriolet, Golf I	Headliner					\$550		
1986-93	HL963	1986-93 Cabriolet, Golf I	Headliner					\$550		
1980-93	PD2062	VW Top Pad with	Cover					\$948		
1980-93	CV2062	1980-93 Cover	Only for 1980-93 VW Top Pad					\$360		
1980-81	B1061	1980-81 Volkswagen	Rabbit, Golf I Top Boot		\$799	\$1,200				
1982-93	B1062	1982-93 Rabbit, Cabriolet, Golf I	Top Boot		\$984	\$1,386				
1954-79	CBLVWRS	Beetle, K. Ghia, Rabbit, Cabriolet	Side Cables					\$151		
1980-93	CBL2062R	1980-93 Rabbit, Cabriolet	Rear Mounting Cable (each)					\$271		
<b>YR</b>	<b>PART NO.</b>	<b>CABRIO/GOLF III 1995-2000</b>		<b>RC</b>	<b>AT</b>	<b>SF</b>	<b>TW</b>	<b>MISC.</b>	<b>HRS.</b>	<b>B/H</b>
1995-00	2064	Cabrio, Golf III	Top for rubber mounting only	\$704	\$762	\$996	\$1,144		6	
1995-00	HL2064	1995-2000 Cabrio, Golf III	Headliner					\$726		
1995-00	CBL2064	1995-2000 Cabrio, Golf III	Side Tension Cables					\$169		
<b>YR</b>	<b>PART NO.</b>	<b>CABRIO/GOLF IV 2001-2002</b>		<b>RC</b>	<b>AT</b>	<b>SF</b>	<b>TW</b>	<b>A5</b>	<b>HRS.</b>	<b>B/H</b>
2001-02	2066	VW Cabrio, Golf IV	Top, with Heated Glass	\$1,438	\$1,569	\$1,732	\$1,878	\$1,967	6	
<b>YR</b>	<b>PART NO.</b>	<b>VOLKSWAGEN NEW BEETLE</b>		<b>SF</b>	<b>TWR</b>	<b>A5</b>			<b>HRS.</b>	<b>B/H</b>
2003-11	2068C	VW Beetle Top	with Heated Glass, POWER FRAME Original German Zippers. Factory Brackets to fit headliner.	\$1,893	\$2,111	\$2,415			8	
2003-11	2068AC	VW Beetle, Top	with Heated Glass, MANUAL FRAME Sewn in front pad. No zippers. Brackets to fit factory headliner.	\$1,967	\$2,230	\$2,552			8	
<b>YR</b>	<b>PART NO.</b>	<b>VOLVO</b>		<b>AT</b>	<b>TW</b>	<b>A5</b>			<b>HRS.</b>	<b>B/H</b>
<b>YR</b>	<b>PART NO.</b>	<b>VOLVO C70</b>		<b>TW</b>	<b>A5</b>				<b>HRS.</b>	<b>B/H</b>
1999-06	8400	Volvo C70 Top	w/Heated Glass Window Sewn-in retainers and original OE style Zipper	\$1,685	\$1,893	\$2,186			8	

VINYL TOPPING CODES

BS	British Everflex
CH	Early Chrysler Crush Grain
EF	Robbins EverFlex Grain Vinyl
JD	Denim Grain Jeep Topping
KV	Pinpoint Grain
SS	Sailcloth Grain
LV	Levant Grain
CG	Crush Grain
CM	Cami for Suzuki Tops
HV	Haartz Twill Grain Vinyl
JP	Crush Grain Jeep Topping



RC Cabrio Grain  
AT TRILOGY Acoustic Twill

EF,HV,KV,RC,SS,AT have 100% Poly Backing

#### CLOTH TOPPING CODES

A5 Haartz A5 German Cloth  
A5B Haartz A5 Acoustic German  
LM Haartz Twillfast JX  
TWR Haartz Twillfast RPC/Z  
HR Haartz ST Cloth, HotRod Colors  
SF Robbins@Sun-Fast Squareweave  
A5S Haartz A5 German Flame Singed  
GR Haartz German Classic  
TW Haartz Twillfast  
ST Haartz Stayfast  
SG Robbins Sun-Fast "G" Twillweave  
SR Robbins Sun-Fast "R" Twillweave Acoustic

#### HEADLINING MATERIAL CODES

HL BLK Black Vinyl  
HL ESB Black Escort Crater Grain Vinyl  
HL VLB Velour Black Cloth  
HL VWB 1994-02 VW Black Cloth  
DANE Dane Cloth  
  
HL WHT White Vinyl  
HL ESW White Escort Crater Grain Vinyl  
HL VLC Velour Charcoal Cloth  
HL VWG 1994-02 VW Keisel (Gray/Tan) Cloth  
BRO Brocade Cloth  
  
HL GRY Gray Vinyl  
HL SEB Sebring Headliner  
HL VLG 1989-93 Opel Gray Cloth  
BOW German Style Bowdrill